

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☒ well other ☐
2. NAME OF OPERATOR
Getty Oil Company
3. ADDRESS OF OPERATOR
P. O. Box 3360, Casper, Wyoming 82602
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1830' FSL + 790' FWL (NWSW)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- | | | |
|----------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input type="checkbox"/> |
| (other) | <input type="checkbox"/> | <input type="checkbox"/> |

5. LEASE
68
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla - B
9. WELL NO.
20-E
10. FIELD OR WILDCAT NAME
Otero Gallup-Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 31-T25N-R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6762' Gr

(NOTE: Report results of multiple completion or zone change on Form 9-330.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Gallup - Set 5 1/2" Baker Model "F" packer @6450'. Spot 400 gal. 15% Acetic Acid from 6314-5914'. Perforate with 98 (0.250" Dia.) Holes at 5994-6001', 6008-10', 6015-20', 6031-38', 6051-68'. 6072-6104', 6108-14', 6139-42', 6170-75', and 6306'-10'. Acidize perforations with 4000 gal. 15% HCL. Frac perforations with 120,000 gal. Nitrified X-linked gel with 144,000# 20-40 sand, 80,000# 10-20 sand & 1,248,000 SCF of N₂. Flushed with 107 BBLs. of 2% KCL water with 400 SCF N₂ per BBL.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Superintendent DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

JAN 27 1974

*See Instructions on Reverse Side

BW

