Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM	1 APPR	OVE	D
udget Bure	eau No.	100	4-013
Expires:	March	31.	1993

Budget Bure	eau No.	100	04-01
Expires:	March	31,	1993

BUREAU OF LAND MANAGEMENT			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals	5. Lease Designation and Serial No. MCARILLA CONTRACT 146 6. If Indian, Allottee or Tribe Name		
1. Type of Well Oil Gas Well Other	7. If Unit or CA, Agreement Designation		
	JICARILLA CONT 146 #33		
2. Name of Operator AMOCO PRODUCTION COMPANY WAYNE BRANAM, RM 1220	9. API Well No.		
AMOCOTHOCOCHOL	3003922521		
3. Address and Telephone No. (303) 830-4912	10. Field and Pool, or Exploratory Area		
P.O. Box 800, Denver, Colorado 80201	BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State		
970 FSL 1120 FEL Sec. 10 T 25N R 🕏 W UNIT P	RIO ARRIBA NM		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION			
Abandonment Recompletion - Value of Intent - Subsequent Report Subsequent Report Altering Casing Other INde: Re	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Sport results of multiple completion on Well Completion or setion Report and Log form. I		

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

AMOCO PROPOSES TO REPAIR THIS WELL PER THE ATTACHED.



	in the same state of	7 5 1995 - 1
		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
4. I hereby certify that the foregoing is true and correct Signed	Title BUSINESS ANALYST Dat	12-21-1994
Approved by Conditions of approval, if any:	Chief, Lands and Mineral Resources	, JAN 2 4 1995'
ritle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfull epresentations as to any matter within its jurisdiction.	o make to any department or agency of the United States any false, ficticious, c	or fraudulent statements or
* S	e Instructions on Reverse	

JICARILLA CONTRACT 146 - 33 SEC 10 - T25N - R5W RIO ARRIBA COUNTY, NM REPAIR WELL PROCEDURE

- 1. TOOH with the 2-1/16" production tbg.
- 2. TIH with bit and scraper for 5-1/2" csg to 5450'. .
- 3. Wireline set a CIBP at 5410'.
- 4. Cap the CIBP with 10' of sand/barite mixture. Bring the mixture up to 5400'. The mixture should be 33% barite and 67% 20/40 sand.
- 5. TIH with muleshoe, SN, and 2-1/16" tbg and land intake at 5340'.
- 6. Swab the well in and RTP.

