5. LEASE

UNITED STATES

	Santa Fe 078913
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	Lindrith B Unit
	8. FARM OR LEASE NAME
1. oil 🔼 gas 🗌 other	9. WELL NO.
2. NAME OF OPERATOR	16
Mobil Producing TX. & N.M. Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 9 Greenway Plaza, Suite 2700, Houston 77046	Chacon-Dakota Associated
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA
below.)	Sec. 21, T24N, R3W
AT SURFACE: 790 FNL + 790 FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same as surface AT TOTAL DEPTH: same as surface	Rio Arriba New Mexico
	14. API NO.
5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD
	7147 GR
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
EST WATER SHUT-OFF	
HOOT OR ACIDIZE	
EPAIR WELL	(NOTE: Report results of multiple completion or zone
JLL OR ALTER CASING	change on Form 9-330)
HANGE ZONES	
BANDON*	
other) run 13-3/8 csg.	
	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent. 	irectionally drilled, give subsurface locations and
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m.	lirectionally drilled, give subsurface locations and to this work.)*
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	firectionally drilled, give subsurface locations and to this work.)* to 305 . Cmt w/ 375 x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg.	firectionally drilled, give subsurface locations and to this work.)* to 305 . Cmt w/ 375 x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	firectionally drilled, give subsurface locations and to this work.)* to 305 . Cmt w/ 375 x B + 2%
including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg 11" hole.	to 305. Cmt w/ 375x B + 2% + BOP to 1000/OK. Cont. drlg.
measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg.	irectionally drilled, give subsurface locations and to this work.)* to 305. Cmt w/ 375x B + 2%
including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertiner 12-4-80 Spud 17½" hole @ 5 p.m. 12-5-80 Ran 7 jts 13-3/8 48# H40 ST&C csg. CaCl2. Cmt. circ. NU + test csg 11" hole.	to 305. Cmt w/ 375x B + 2% + BOP to 1000/OK. Cont. drlg.