$\{\chi_{n}(\omega)\}^{-1}(\omega)$

Jic. Tribal Cont. #123

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME Jicarilla 123 C
well gas	9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	28 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87401	Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 6, T-25-N, R-4-W NMPM
AT SURFACE: 1800'S, 1580'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6827 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	p. p. c.
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is discussed and true vertical depths for all markers and zones pertinent	irectionally drilled, give subsurface locations and
9-6-81: T.D. 7741'. Ran 199 joints of 4 1/2", 7729' set at 7741'. Float collar set 3428-6015'. Cemented 1st stage w/ 515 cmt, 3rd stage w/430 cf. cmt. WOC 18	at 7741', stage tools set at cf. cmt., 2nd stage <u>w/55</u> 1 cf.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	-
	erk dateSeptember 8, 1981
(This space for Federal or State off	
	DATE
CONDITIONS OF APPROVAL, IF ANY:	

*See Instructions on Reverse Side