Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instance of the Instance of

SUBMIT IN TRÍPLICATE* instructions on

Form approved. Budget Bureau No.

U. LEASE	DESIGNATION	AND	SERIA
Lease	: Contrac	21	69

GEOLOGICAL SURVEY	Lease Contract 69		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL GAS WELL OTHER	7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR Gulf Oil Corporation	8. FARM OR LEASE NAME Apache Federal		
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, NM 88240	9. WELL NO. 12E		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990 FST & 990 FMT	10. FIELD AND FOOL, OR WILDCAT Basin Dakota		
990' FSL & 990' FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, ET, GR, etc.) 6521 GL	Sec 17-T24N-R5W 12. COUNTY OF PARISH 13. STATE RIO Arriba NM		
16. Charle American De Toll Control De	01. 5		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

				•	
NOTICE OF INTENTION TO:		 SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)		REPAIRING WELL ALTERING CASING ABANDONMENT*	XX
(Other)		(Note: Report res Completion or Reco	uits of multiple impletion Report	completion on Well t and Log form.)	1

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 5-12-81. RU & ran 148 & 1 cut joint $5\frac{1}{2}$ " 15.5# K-55 LT&C (6768') set at 6782', FC @ 6736', DV @ 4701'. Cement 1st stage with 400 sacks "B" with 4% gel 0.5% D-64 and 200 sacks "B" with 0.5% D-65. Plug down 1:30 P.M., 5-13-81. Circulate out 50 sacks excess above DV tool to surface. Cement 2nd stage with 900 sacks 16% gel Gulfmix and 100 sacks "B" neat. Plug down 5:00 P.M., 5-13-81. Circulate cement to surface. WOC 18 hours. Test casing 4500#.



•	•	
3. I hereby certify that the foregoing is true and correct		
SIGNED T. L. Pouston	TITLE Area	Drilling Superintendent DATE 5-21-81
(This space for Federal or State office use)		ACCEPTED FOR RECORD
•		
APPROVED BY	TITLE	MRYTE 5 1981
		\$ I I I A A A

MINIUCO

FARMINGTON DISTRICT