

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. NAME OF OPERATOR CONOCO INC	3. ADDRESS OF OPERATOR P.O. BOX 460, HOBBS, NM 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit N	5. LEASE DESIGNATION AND SERIAL NO. CONTRACT 41	6. IF INDIAN, ALLOTTEE OR TRIBE NAME JICARILLA APACHE	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME JICARILLA 30	9. WELL NO. 16	10. FIELD AND POOL, OR WILDCAT UNDES. MESAVERDE / UNDES. CHACRA	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SECTION 29 T25N, R4W	12. COUNTY OR PARISH RIO ARriba	13. STATE NM
14. PERMIT NO. 30-39-22719	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 660' FSL + 1980' FWL 6922 GL											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) RECOMPLETION IN MESAVERDE/CHACRA

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) MIRU RIH W/ BIT + SCRAPER TO PBTD (7562'). SET RBP @ 6425'. DUMP 2 SX SAND ON TOP. RUN GR/CCL LOG FROM 5500'-3500'.
- 2) PERF CLIFF HOUSE @ 4737'-4778' W/ 2 JSPF BREAKDOWN PERFS W/ 40 BBL 7 1/2% HCL-NE-FE. FRAC CLIFF HOUSE W/ 40,000 # 20/40 SAND @ 20-25 BPM. RUN OPEN FLOW POTENTIAL AND 7 DAY SHUT-IN BOTTOM HOLE PRESSURE TEST.
- 3) SET RBP @ 4050'. PERF CHACRA @ 3978'-4002'. BREAKDOWN PERFS W/ 25 BBL 7 1/2% HCL-NE-FE. FRAC CHACRA W/ 40,000 # 20/40 SAND @ 20-25 BPM. RUN OPEN FLOW POTENTIAL AND 7 DAY SHUT-IN BOTTOM HOLE PRESSURE TEST.
- 4) RELEASE RBP @ 4050'. RIH W/ 2 3/8" TBG AND PUT WELL ON PRODUCTION.

18. I hereby certify that the foregoing is true and correct

SIGNED Mafine Simpson for D.F. Finney TITLE Adm. Supervisor

DATE 9/8/88

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

NMOCC

*See Instructions on Reverse Side

SEP 15 1988

AREA MANAGER

WELL: Jicarilla 30 No. 16 CONOCO WI: 100 % PREPARED BY: RLT
 STATUS: 0 POOL: Und. Mesaverde / Otero Chacra DATE: 9/7/88
 LOCATION: 660' FSL and 1980' FWL SECTION: 15 TOWNSHIP: 25N RANGE: 4W
 COUNTY: Rio Arriba STATE: NM FORMERLY: 0
 DATUM: 6936 ft GROUND LEVEL: 6922 ft TD: 7575 ft PBTD: 7562 ft

WELLBORE DIAGRAM

PULLING AND WORKOVER HISTORY

DATE

WORK PERFORMED

No Remedial Activities Reported

< 8 5/8" 24# csg
 @ 295' w/ 220 sx cmt

TOC @ 1850'

[DV Tool
 @ 4997'

2 3/8" tbq
 well on plunger lift

Gallup Perfs: 6475'-6745'
 1 JSPF (25 holes)

Dakota Perfs: 7295'-7502'
 1 JSPF (21 holes)

(5 1/2" 15.5# and 17# csg
 @ 7575' w/ 1800 sx cmt

COMMENTS:

DV Tool is located right below Cliffhouse interval.

Typical Dual Jicarilla Recompletion

