UNITED STATES

****** =	(5. 11/31)
DEPARTMENT OF THE INTERIOR	N00-C-14-20-8451
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICALE CONVEY	THE WARE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	TO STATE TO THE TOTAL THE TOTAL TO THE TOTAL THE TOTAL TO THE TOTAL TH
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331–C for such proposals -	8. FARM OR LEASE NAME
1 oil	South Blanco Navajo 31
1. oil gas other other	9. WELL NO.
2. NAME OF OPERATOR	2 2
Mesa Petroleum Co.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Lybrook-Gallup Extension
1660 Lincoln St. #2800, Denver CO 80264 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec31-T24N-R7W
AT SURFACE: 1660' FNL & 940' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	1 24. ATT 140.
REPORT, OR OTHER DATA	15 FIFWATIONS OF THE STATE OF T
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6950' KB
TEST WATER SHUT-OFF	• .
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	1982
CHANGE ZONES	100/2
ABANDON*	<u></u>
other) Fracture Treat Mayre Sand	Contraction of the second of t
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	rectionally drilled give subsurface locations and
This is a substitute Sundry Notice for Notice radioactive tracer survey run across perforation fractured. Survey indicated that Mayre Sand himitially completed. Set bridge plug at 5550' interval at 5517-5528'. Fractured interval with rock salt in the first 500 gals and 800 SCF/bt 19,380 gals 70 quality foam containing 25,000# Iridium 192 in the last 15,000# sand. Request assessment sent June 18,1982.	ions to see if entire interval was had not fractured when well was , packer at 5440'. Mayre Sand ith 2000 gals pre-pad with 500# ol N2 in all 2000 gals. Pumped # 20-40 sand and 15 millicuries
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED Randy Morlinger TITLE Reg. Coordina	itor DATE June 23, 1982
(This space for Federal or State office use)	
APPROVED BY ACCEPTED FOR RECORD TITLE	DATE
HIM 6 A 1002	
JUN 3 O 1982	

*See Instructions on Reverse Side



