Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

FEB 1 6 1999 It Onit or CA/Agreement, Name as

SUBMIT IN T	RIPLICATE - Other Insti	ructions on reverse	e side	1998 Ho.	nit or CA/Agreement, Name and/or No	
1. Type of Well Oil Well KGas Well			H. COM	100		
2. Name of Operator NM&O Operating Company					8. Well Name and No. Gavilan 9. API Well No.	
	Tulsa, OK 74103			·	9. API Well No #1 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 930' FNL & 910' FEL Section 26-T25N-R2W				Me 11. Count Ri	Mesa Verde 11. County or Parish, State Rio Arriba County	
12. CHECK AI	PPROPRIATE BOX(ES) TO			REPORT, C	OR OTHER DATA	
	TYPE OF ACTION					
Notice of Intent Subsequent Report Final Abandonment Notice B. Describe Proposed or Complete If the proposal is to deepen direct	Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Ab Water Disposal	Pandon	Water Shut-Off Well Integrity Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

11-30-98 thru 12-05-98: MIRU Well Service Unit. Nipple up BOP. POH w/tbg. MIRU Halliburton. Run collar locator. RIH w/CIBP & set @ 7781'. TIH w/dump bailer and dump 2 sx cmt on top. RIH w/CIBP and set @ 6751'. TIH w/dump bailer and dump 2 sx on top. Load hole with lease water. Run CBL from 5979' to 2400'. RIH and perforate Mesa Verde formation intervals 5759'-5771' and 5784'-5794' w/ 4HPF. RIH w/tbg. & packer. Spot 2 bbls 15% HCL across Mesa Verde interval perforations. Set packer and pump 2000 gal 15% HCL followed by 54 bbl lease water into perforations. Flowed and swabbed back well. Final test: 100 to 125 mcfd. POH w/tbg. and packer. TIH w/SN and tbg. and land @ 5983'. Nipple down BOP, nipple up wellhead. Release Well Service Unit. Shut-in Well evaluating fracture

14. I hereby certify that the foregoing is true and correct						
Name (Printed/Typed)	Title	Title				
Larry D. Sweet	President					
Signature						
	Date	12/22/9x.				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by // / O /						
1/2/ 2010		Tillands and Mineral Resources	FEB 1 1 1999			
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.		Office				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and	t millfullures					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.