5 BLM; 1 F Form 3169-5 (November 1983						Pudget Bureau No. 1004-0135 Expires August 31, 1985
(Formerly 9-33					1000 60 14-	3. LEFEE DESIGNATION AND SEELL NO.
(De not	SUNDRY NO	OTICES AND REPORTED TO A SECULIAR TO A SECUL	ORIS ON	WELLS to a different rese	rvolr.	G. IF INDIAN, ALLOTTES OR TRIBS NAME
I.	CAS OTES		j	UL 0 1 1985	9	T. UNIT AGREEMENT NAME
	BCO, Inc. BUREAU OF LAND MANAGE FARMINGTON RESOURCE				VIENI	8. FARM OR LEASE NAME Federal 3-21
3. ADDRESS OF	PERATOR			-	REA	9. WELL HO.
135 Grant Avenue, Santa Fe, New Mexico 87501 6. Incation of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						5 10. FIRLD AND POOL, OR WILDCOF ESCRITO Gallup 11. EBC. T. R. M. OR RLT. AND
		, Sec 21, T24N, R7W, N.M.P.M., Rio Arriba County			Sec 21, T24N, R7W	
14. PERMIT NO.		7285 GR				Rio Arriba New Mexic
16.	Check	Appropriate Box To I	Indicate Natu	re of Notice, R	•	ther Data
TEST WATER	BEUT-OFF	PCLL OR ALTER CASING	WATER SHO		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	REPAIRING WELL
FRACTURE TR BHOOT OR AC	I	MULTIPLE COMPLETE ARANDON®		PRACTURE TREAS	V	ALTERING CABING
REPAIR WELL		CHANGE PLANS		(Other) (Note: Re	port results	of multiple completion on Well
17. DESCRIBE PROP proposed w nent to this	ork. It well us dire	operations (Clearly state ectionally drilled, give sub-	all pertinent de surface locations	Completion	or Recomple	ction Report and Log form.) including estimated date of starting and depths for all markers and zones perti
6/17/85	Drilled out	DV tools.				
6/17/85	Ran Cement Bond Log Computer Laser . Bluejet to mail two copies of said log to the BLM and one copy to OCC in Aztec. Determined PBTD is 6175 '. Cement tops determined to be as follows: TD to 5353 and stage 5174 to surface as reported on $5/24/85$ Sundry Notice. Pressure tested at 3000 #'s and held. Perforated with one 3 1/8" .32" select fire shot at 6099 , 6082 , 6077 , 6072 , 6067 , 6061 , 5964 , 5942 , 5937 , 5932 , 5876 , 5870 ,					
6/18/85	Spotted 1500 gallons of 7% HCL double inhibited acid. Broke down perforations. A straddle packer verified 6099, 6082, 6077, were broken down. Straddle packer failed and the rest were not individually tested.					
6/19/85	Treated 64,000 gallons of water with 16 gallons Excide, 64 gallons ASP-522, gallons LT-22, 10,660 #'s KCL, 320 #'s B-5, 1280 #'s J-5, 65 #'s B-11. Sand water foam fracked, (75%) 5870-6099 with 71,340 gallons of foam, 54,000 #'s 12-20 sand, 1,400,930 standard cubic feet of nitrogen and 108 gallons FRAC FOAM I. Average treating pressure 3850 #'s at 50 foam Bbls. per minute. Well sanded off due to equipment problems.					
/20/85	Broke down all perforations with a Straddle packer to determine all holes broken down as well as determine their calculated size.					
<u>/23/85</u>	Had 42,400 gallons of treated water remaining from 6/19/85 frac. Treated 25,200 gallons of water with 6 gallons Excide, 22 gallons ASP-522 gallons LT-22 and 3785#'s KCL. Treated the 64,000 gallons of treated water described above with 320#'s B-5, 1280#'s J-5, 64#'s B-11. Sand water foam fracked (75%) 5870-6099 with 100,670 gallons of foam 106,000#'s 12-20 Sand, 2,193,000 standard cubic feet of nitrogen and 165 gallons FRAC FOAM I. Average treating pressure 4800 #'s at 30 foam Bbls. per minute. Well sanded off.					
<u>6/26/</u> 85	Potentialed	well at <u>38</u> B0	OPD, <u>78</u>			
				Thomas of the state of the stat		
18. I bereby certif	that the foregoing	is true and correct			JUL	05 1985
SIGNED EI	^ ^ ^	R V. I	TLE Comp	roller		6/28/85
	r Federal or State o	•				
APPROVED B' CONDITIONS	OF APPROVAL, IF		TLE			<u> </u>
					FARMI	Nation mayoute intel
	•	*See In	istructions on	Reverse Side	ВҮ	V .

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the