Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO 1004-0135 Expires: Nov ember 30, 2000

5.	Lease Serial No.
	NMSF078885

	NOTICES AND REPOR is form for proposals to d		NMSF07888	)
abandoned we	II. Use form 3160-3 (APD)	) for such proposals.	6. If Indian, Allotte	e or Tribe Name
SUBMIT IN TRI	7. If Unit or CA/A NMNM78383	green nent, Name and/or No.		
. Type of Well ☐ Oil Well ☑ Gas Well ☐ Oth		8. Well Name and Y CANYON LA	No. RGO UNIT 250E	
Name of Operator BURLINGTON RESOURCES	Contact: (	None Specified)	9. API Well No. 30-039-25720	)-0( -C1
a. Address P. O. BOX 4289 FARMINGTON, NM 87499	3b. Phone No. (include area cod Ph: 505.326.9700	e) 10. Field and Pool, BLANCO	10. Field and Pool, or Exploratory BLANCO	
Location of Well /Footage, Sec., 7		11. County or Paris	11. County or Parish, and State	
Sec 1 T25N R6W Mer SESE		RIO ARRIBA	RIO ARRIBA CCUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION		ТҮРЕ С	DF ACTION	
□ Notice of Intent	<b>⊠</b> Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	<ul><li>☐ Plug and Abandon</li><li>☐ Plug Back</li></ul>	☐ Temporarily Abandon ☐ Water Disposal	
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8-24-01 MIRU, ND WH, NU E	rk will be performed er provide the deparations. If the operation resubandonment Notices shall be filed in all inspection.)  BOP, TIH, tag up, TOOH with the performance in the performa	he Bond No. on file with BLM/Bl ults in a multiple completion or re- d only after all requirements, inclu-	sured and true vertical depths of all pe A. Required subsequent reports shall completion in a new interval, a Form i iding reclamation, have been complete II. SD for weekend.	be f led within 30 days 160.4 shall be filed once id, and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8-24-01 MIRU, ND WH, NU E	rk will be performed er provide the deparations. If the operation resubandonment Notices shall be filed inal inspection.)  BOP, TIH, tag up, TOOH w., Pump 500 gal acid. Displa	he Bond No. on file with BLM/BI ults in a multiple completion or re- d only after all requirements, inclu- /2 3/8" tbg. TIH w/3 7/8" mi ace w/5 bbl wtr. TOOH w/m	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1	rtine at markers and zones. be f led within 30 days 1160-4 shall be filed once and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 8-24-01 MIRU. ND WH. NU E 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236	rk will be performed or provide the doperations. If the operation results bandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displation of the plant of	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, include 1 2 3/8" tbg. TIH w/3 7/8" minace w/5 bbl wtr. TOOH w/m Rig released.	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1	rtine at markers and zones. be f led within 30 days \$160-4 shall be filed once ad, and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 8-24-01 MIRU. ND WH. NU B 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236)	rk will be performed or provide the doperations. If the operation resubandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displate.  '). N D BOP. NU WH. RD. filed	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, included the second of the sec	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1	rtine at markers and zones. be f led within 30 days 1160-4 shall be filed once and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 8-24-01 MIRU. ND WH. NU B 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236)	rk will be performed or provide the doperations. If the operation resubandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displation of the provided filed f	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, included the second of the sec	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-9  III. Information System to the Farmington	rtine at markers and zones. be f led within 30 days 1160-4 shall be filed once and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 8-24-01 MIRU. ND WH. NU B 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236	rk will be performed or provide the doperations. If the operation resubandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displation of the provided filed f	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, included the second of the sec	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1  III. TIH w/232 jts 2 3/8" 4.7# J-1  III. TIH w/232 jts 2 3/8" 4.7# J-1	rtine at markers and zones. be f led within 30 days 1160-4 shall be filed once and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 8-24-01 MIRU. ND WH. NU E 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236)  4. Thereby certify that the foregoing is Cor Name (Printed/Typed) (None Sp	rk will be performed or provide the operations. If the operation resubandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displation of the provided of the provided in the pro	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, included the second of the sec	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1 iiII. TIH w/232 jts 2 3/8" 4.7# J-1 ii	rtine at markers and zones, be f led within 30 days 1160-4 shall be filed once id, and the operator has
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 8-24-01 MIRU. ND WH. NU E 8-27-01 TIH, blow well & CO landed @ 7237'. (SN @ 7236)  4. Thereby certify that the foregoing is Cor Name (Printed/Typed) (None Sp	rk will be performed or provide the operations. If the operation resubandonment Notices shall be filed final inspection.)  BOP. TIH, tag up. TOOH w., Pump 500 gal acid. Displation of the provided of the provided in the pro	he Bond No. on file with BLM/BI lits in a multiple completion or red only after all requirements, included the second of the sec	A. Required subsequent reports shall completion in a new interval, a Form inding reclamation, have been completed.  II. SD for weekend.  III. TIH w/232 jts 2 3/8" 4.7# J-1 iiII. TIH w/232 jts 2 3/8" 4.7# J-1 ii	rtine it markers and zones. be f led within 30 days st 160.4 shall be filed once and the operator has

\*\* REVISED \*\* REVISED \*\* REVISED \*\* REVISED \*\* REVISED \*\* REVISED \*\*