

THIS IS THE CHARLES M #3

THERE IS A LOT OF INFORMATION MISSING

THE WELL TOOK SEVERAL YEARS, TWO SUPERVISORS, 3 LAWYERS
TO FINALLY GET IT PLUGGED.

THERE WAS NO BOND TO BEGIN WITH.

PAPER WAS SENT IN WITH THE WRONG WELL NAME.

(DAVIS #1, CHARLES M #1) BOTH WRONG NAMES.
CHARLES M #1 WAS EVEN USED IN AN ORDER. IT WAS WRONG

API # 30-039-82310 NOT IN ONGARD AS OF 3-21-02