Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on re-

Form approved,
Budget Bureau No. 42-R1424.

DATE ___

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (T. UNIT AGREEMENT NAME East Bisti Unit 8. FARM OR LEASE NAME 100 100 100 100 100 11. Sec also space 17 below.) At surface 660' FSL & 1980' FWL Section 1-24N-10W Section 1-24N-10W Section 1-24N-10W 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY			5. LEASE DESIGNATION AND SERIAL NO. SF 078301		
Other Section 1-24X-10W 16. FERNIT NO. Check Appropriate Box To Indicate Notice, Report, or Notice, Report, or Notice of Intertion of	SUNDRY NOTIC	CES AND REPORTS C	N WELLS lek to a different reservoir. oposals.)	6. IF INDIAN, ALLOTTEE OR TRIBLE NAME		
Skelly 0il Company 3. Addition Street-Denver, Colorado 80203 4. Incoln Street Denver, Colorado 80203 4. Incoln Street Denver	OIL GAS WELL OTHER			East Bisti Unit		
1860 Lincoln Street-Denver, Colorado 80203 A magniso we that (their bording cirally and is accordance with any State requirements.* Section 1-24%-10W 11. SECTION 1-24%-10W 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Scriego in intervior for the Scriego intervior for the Scriego in intervior in the Scriego in the Scriego in Inter	Skelly Oil Company			9. WELL NO.	,,	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.) 12. COUNTY OF PARSINI 13. STATE 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PEACTER THEAT SHOOTING OF ACTIVE COMPLETE AMAXON' CHANCE FLANS (Other) (Other) (Note: Report results of multiple completion on Well (Note: Report results of multiple completion	1860 Lincoln Street-Denver, Colorado 80203 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)			Bisti Lower Gallup 11. SEC., T., R., M., OR BLK. AND		
18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Notice of Intextion to: TEST WATER SHUT-OFF PRACTIES THEAT SHOOT OR ACIDEZE REPAIR WELL (Other) TOUGHER PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and size pertinent depute of Montage Prince of Subscribes Works. If well is directionally drilled, give subsurface locations and measured and true vertical depute for all markers and acouse pertinent on this work.) All depths shown are from ground level 9/17/71 MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug 5498-5398' Pulled 2" tubing, Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 5-1/2" casing 1829-1830' with 4 shots. Perforated 1059-1060' with 4 shots. Spotted cement plug 1830-1680' and from 1060-960'. Shot 5-1/2" casing off at 930'. Spotted cement plug 960-860', 50' inside casing stub and 50' above casing stub. Pulled total of 23 joints (930') 5-1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 9/17/71.	660' FSL & 1980' FWL			Section 1-2	4N-10W	
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTICE THAT SHOOT OR ACIDIZIE REPART WELL CHANGE PLANS (Other) 17. DESCRIBE PROPER THOUSE OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including extrapated date of starting any performance of this work.)* All depths shown are from ground level 9/17/71 MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug 5498-5398' Pulled 2" tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 5-1/2" casing 1829-1830' with 4 shots. Perforated 1059-1060' with 4 shots. Spotted cement plug 1830-1680' and from 1060-960'. Shot 5-1/2" casing off at 930'. Spotted cement plug 960-860', 50' inside casing stub and 50' above casing stub. Pulled total of 23 joints (930') 5-1/2" casing. Installed dry hole marker. Lead Clerk	14. PERMIT NO.				New Hexico	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBLE PROPOSED OR COMPLETE DESCRIBORS of this subsurface locations and measured and true vertical depths for all markers and zones peripented to this work.)* All depths shown are from ground level 9/17/71 MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug 5498-5398' Pulled 2" tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 5-1/2" casing 1829-1830' with 4 shots. Perforated 1059-1060' with 4 shots. Spotted cement plug 1830-1680' and from 1060-960'. Shot 5-1/2" casing off at 930'. Spotted cement plug 960-860', 50' inside casing stub and 50' above casing stub. Pulled total of 23 joints (930') 5-1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 9/17/71.	•			•	÷.	
9/17/71 MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug 5498-5398' Pulled 2" tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 5-1/2" casing 1829-1830' with 4 shots. Perforated 1059-1060' with 4 shots. Spotted cement plug 1830-1680' and from 1060-960'. Shot 5-1/2" casing off at 930'. Spotted cement plug 960-860', 50' inside casing stub and 50' above casing stub. Pulled total of 23 joints (930') 5-1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 9/17/71.	FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction	BANDON* HANGE PLANS	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report result Completion or Recompletion or Recomp	ALTERING CA ABANDONMEN ABOUT So of multiple completion pletion Report and Log for a including estimated dat	on Well	
Pulled 2" tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 5-1/2" casing 1829-1830' with 4 shots. Perforated 1059-1060' with 4 shots. Spotted cement plug 1830-1680' and from 1060-960'. Shot 5-1/2" casing off at 930'. Spotted cement plug 960-860', 50' inside casing stub and 50' above casing stub. Pulled total of 23 joints (930') 5-1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 9/17/71.	All depths shown are	from ground level	·			
Completed P&A 9/17/71. 18. I hereby certify that, the foregoing is true and correct Lead Clerk 11-2-71	Pulled 2" tubing. Wo perforated 5-1/2" cas shots. Spotted cemen at 930'. Spotted cem stub. Pulled total o	rked 5-1/2" casing ting 1829-1830' with t plug 1830-1680' and ent plug 960-860', 5 f 23 joints (930') 5	to free same. Rigged 4 shots. Perforated d from 1060-960'. 60' inside casing standard casing.	l up blue jet and 1059-1060' with Shot 5-1/2" casinb and 50' above	nd ih 4 ing off	
18. I hereby certify that, the foregoing is true and correct Lead Clerk	•		;. Installed dry no	in marker		
/ W R . 1 \ Lead Clerk	Completed P&A 9/17/71				3	
	18. I hereby certify that, the foregoing is		Lead Clerk	DATE	-71	

TITLE ___