

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-5805	E-6234

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Schermerhorn Oil Corporation</b>		8. Farm or Lease Name <b>Other State</b>
3. Address of Operator <b>P. O. Box 287 Tulsa, Oklahoma 74101</b>		9. Well No. <b>#1</b>
4. Location of Well UNIT LETTER <b>A</b> <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>790</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>25N</b> RANGE <b>7W</b> NMPM.		10. Field and Pool, or Wildcat <b>Ballard</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6652 Gr.</b>		12. County <b>Rio Arriba</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Check 2 7/8" Casing
2. Set 25 sack plug on bottom.
3. Cut and pull casing if free more than 1000'.
4. Set 25 sack plug at 1200' - or cut off point.  
Set 25 sack plug at 120'  
Set surface marker in 5 sack plug.
5. If casing not free below 1000', fill casing with cement.
6. Clean and level location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

For the express purpose to salvage - plug and abandonment this well only.

SIGNED James W. Copeland TITLE Casing Pulling Contractor DATE 3/16/65

APPROVED BY Emory C. Arnold TITLE Sup. Dist. III DATE 3-30-65  
CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-5805	E-6234

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Schmerhorn Oil Corporation	8. Farm or Lease Name Othel State
3. Address of Operator P. O. Box 237 Tulsa, Oklahoma 74101	9. Well No. #1
4. Location of Well UNIT LETTER <u>A</u> , <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>790</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>25N</u> RANGE <u>7W</u> NMPM.	10. Field and Pool, or Wildcat Ballard
15. Elevation (Show whether DF, RT, GR, etc.) 6652 Gr.	12. County Rio Arriba

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Checked 2 7/8" casing - ran weight to 2184 - stopped.
2. Ran 1" and pumped 25 sacks on bottom - well dead.
3. Worked 2 7/8" and ran shot to 812 - would not work on down - cement scale in pipe.  
Shot at 808 - pulled 2 jts.
4. Pumped in 25 sack plug.
5. Pulled remainder 2 7/8 to 128'.
6. Set 25 sack plug, cement filled hole.
7. Placed marker in surface and welded.
8. Cleaned location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
For express purpose of salvage - Plug & Abandonment of this well only.

SIGNED <u>James H. Cleveland</u>	TITLE <u>Owner</u>	DATE <u>4/29/65</u>
APPROVED BY <u>Ernest C. Amey</u>	TITLE <u>Sgt. Pitt</u>	DATE <u>4-30-65</u>
CONDITIONS OF APPROVAL, IF ANY:		