NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

		1		
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT OF CAS	T ON RESULT OF TEST ING SHUT-OFF	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT OPERAT	FON RECOMPLETION FION	REPORT ON (Other)	
		December 22, 1955	Farmington, New Mex	ico
Following is a report or	n the work done and the resu	(Date) alts obtained under the heading r	(Place)	
	atural Gas Company		y State	
(Con Company †	npany or Operator)		(Lease) in the 1/4 SE 1/4 of Sec.	16
25N , R. 7W , NM	· ·	Pool,	Rio Arriba	.Coun
The Dates of this work were a	s folows: 9 -26-5 5			
			(Cross out incorrect words)	
Total Bepth 2587	···	OF WORK DONE AND RESU		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT Of the count o	OF WORK DONE AND RESUR	LTS OBTAINED with 75 sacks regular cemer	
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT O	OF WORK DONE AND RESUR		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT Of the count o	OF WORK DONE AND RESUR		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT Of the count o	OF WORK DONE AND RESUR		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT Of the count o	OF WORK DONE AND RESUR		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3	DETAILED ACCOUNT Of the count o	OF WORK DONE AND RESUR		
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3 Top of cement by	DETAILED ACCOUNT Of 1. 7. 7. 7. 7. 7. 7. 7. 7. 7.	OF WORK DONE AND RESUR	with 75 sacks regular cemer	
Total Bepth 2587 Ran 80 joints 7" 75 sacks Pozmix. Held 1000# for 3 Top of cement by Witnessed by	DETAILED ACCOUNT Of the count o	(2578') set at 2588' at 660'. Paso Natural Gas Com	Tool Pusher (Title)	at,
Total Bepth 2587 Ran 80 joints 7" 75 sacks Posmix. Held 1000# for 3 Top of cement by Witnessed by	DETAILED ACCOUNT (, 20#, J-55 casing 0 minutes. temperature survey	(2578') set at 2588' at 660'. Paso Natural Gas Com (Company) I hereby certify that to the best of my k	Tool Pusher (Title) At the information given above is true and comowledge.	at,
Total Bepth 2587 Ran 80 joints 7" 75 sacks Pozmix. Held 1000# for 3 Top of cement by Witnessed by H. L. M	DETAILED ACCOUNT Of 1. , 20#, J-55 casing 0 minutes. temperature survey (Name)	(2578') set at 2588' at 660'. Paso Natural Gas Com (Company) I hereby certify that to the best of my k Name	Tool Pusher (Title)	omple