UNITED STATES SUBMIT IN TRIPLICATE* COther Instructions on reduced Budget Bureau No. 42-R1424. DEPARTMENT OF THE INTERIOR (Other Instructions on reduced by the submitted by

SIIND			OL A E 1		NM 04073								
SUNDRY NOTICES AND REPORTS ON WELLS (Do not see this form for proposals to drift or to deepen or plug back to a different reservoir, Use "APPLICATION FOR PERMIT -" for such proposals.) (H. WELL WELL X OTHER 2. NAME OF OPERATOR Lynco Oil Corporation (Mountain States Matt Ga. 3. ADDRESS OF OPERATOR 5290 DTC Parkway, Bldg. #2, Englewood, Colorado 80111 4. to ation of well (Report location clearly and in accordance with any State requirements.* 825 FNL and 751 FEL					6. IS INDIAN, ALLOTTE	E OR TRIBE NAME							
					,								
					7. UNIT AGREEMENT NAME								
					S. FARM OR LEASE NAME								
					Federal E 9. WELL NO. 2 10. FIELD AND POOL, OR WILDCAT Cavilan P.C. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA								
												31, 26N-2W	
											m on otal	12. COUNTY OR PARISI	3 13. STATE
							4. PERMIT NO		15. ELEVATIONS (Sh		r, da, edc.)	Rio Arriba	New Mexic
							j	Check	Appropriate Box To	Indicate Na	ture of Notice, Report, o		
NO	TICE OF IN	ENTION TO:		SUBS	SEQUENT REPORT OF:	,							
TEST WATER SHUT-OFF	. 1	PULL OR ALTER CASING	ə	WATER SHUT-OFF	REPAIRING	WELL.							
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	- ALTERING C								
SHOOT OF ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ABANDONME	NT* X							
SEPAIR WELL		CHANGE PLANS	:	(Other) (Nore: Report rest	ults of multiple completion	on Well							
(tither)				Completion or Reco details, and give pertinent da as and measured at d true ver	mpletion Report and Log 10	rm.)							
		_		(20	000 2020 2 052 30	163)							
Ojo Aloma	(3580-1 was cut sack p	3750) was cover ; @ 1405 and proposed to the contract of the coverage of the contract of the coverage of the c	red durin ulled. A	s perforations (39 g primary cementin 25 sack plug was 8 surface casing a	ng job (3400 ceπ placed across ca	ment top).							
Ojo Aloma 4^{1}_{2} casing stub. 925	(3580-1 was cut sack p	3750) was cover ; @ 1405 and proposed to the contract of the coverage of the contract of the coverage of the c	red durin ulled. A	g primary cementin 25 sack plug was	ng job (3400 ceπ placed across ca	ment top).							

*See Instructions on Reverse Side

NMOCD