

APPROVED

Budget Bureau No. 42-R-359.2.
Approval expires 12-31-55.Form 9-331b
(April 1952) **JOHN S. J. W. LONG**

(SUBMIT IN TRIPLICATE)

Indian Agency **Jicarilla**
TribalAllottee _____
Lease No. **Contract 184**
Tr 251

ACTING DISTRICT ENGINEER

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 15, 19 **56****Ohio Jicarilla**Well No. **6** is located **1650** ft. from **NE** line and **1650** ft. from **EW** line of sec. **24****SE - Sec. 24**
(1/4 Sec. and Sec. No.)**26N**
(Twp.)**SW**
(Range)

(Meridian)

Jicarilla
(Field)**Rio Arriba**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the ~~derrick floor~~ **KB** above sea level is **6696** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1/20/56 Perforated casing 3050-51' w/4 holes, set packer 2975' broke formation w/1000#, 2 bpm, squeezed in 100 sacks, 90 into formation, 10 sack plug in pipe final pressure 3000#. Drilled cement, cleaned out sand, blew well 1 hr, killed itself. Shudded down, blew 45 mins., killed again.

1/24/56 Re-squeezed thru casing shoe. Filled bottom w/29 sack sand, set tool 2974', broke formation 1400#, 1 bpm, staged squeezed 130 sack cement 3 1/2 hrs., max. press. 2000#, completed 8 p.m. 1/24/56. Drilled plug, cleaned out sand, Tried to test. Shudded, well blew, killed itself.

Temporarily suspended February 11, 1956, until further work performed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Ohio Oil Company**Address **P. O. Box 120****Casper, Wyoming**COPY (ORIGINAL SIGNED)
M. J. BOYCE

By

Title **Division Superintendent of**
Production