(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Allottee **Jicarilla** Tribal Lease No. **Contract** 110

SUNDRY NOTICES AND REPORTS ON WELLS

		1 11			
	ION TO DRILL	i	•	F WATER SHUT-OFF	
	ION TO CHANGE PLANS	}		F SHOOTING OR ACID	
	ION TO TEST WATER SHUT-OFF		•	F ALTERING CASING	1 2 2
	ION TO REDRILL OR REPAIR WEL	1	•	F REDRILLING OR RE	PAIR
-	ION TO SHOOT OR ACIDIZE	i ii	SEQUENT REPORT OF		
·	ION TO PULL OR ALTER CASING.	SUPI	PLEMENTARY WELL I	HISTORY	
AOTICE OF INTENT	TON TO ABANDON WELL				
	(INDICATE ABOVE BY CH	IECK MARK NATURE O	F REPORT, NOTICE, O	OR OTHER DATA)	
		***************************************	J	hly 19th	, 195
'ell No 7 :	is located 990	ft. from ${S \brack S}$	line and 990.	ft. from EW 1	ine of sec
/4 SE/4 (% Sec. and	Bec. 20 261 Bec. No.) (Twp.)	(Range)	N	M.P.K.	
Blanco I	PC Rut.	No Art	riba	Haw	Mexico
(Field	i)	(County or Subdivis		(State or T	
tate names of and	of the derrick floor above	DETAILS OF	WORK	posed casings; indicat c)	te mudding jobs, come
tate names of and	expected depths to objective sand	DETAILS OF day show sizes, weights, and all other impo	WORK s, and lengths of proportant proposed work	of 8-5/8"	OD 2NA
_	expected depths to objective sand ing point TD 106; REB. B-40 casing at	DETAILS OF da; show sizes, weight: ts, and all other impo Set 3 join 106' REB surface. on casing t	WORK s, and lengths of projectant proposed work ats 96.5' with 70 s	of 8-5/8" acks comer	OÐ 24# it,
5-28-57 6-11-57	TD 1061 REB. H-40 casing at circulated to	DETAILS OF da; show sizes, weight to, and all other impo Set 3 join 106' REB surface. A casing t	WORK s, and lengths of proposed work ats 96.5' with 70 s	of 8-5/8" acks comes No pressur RE OIL CON OIS	OÐ 24# it,
5-28-57 6-11-57	TD 106† REB. H-40 casing at circulated to Pressured up cin 30 minutes.	DETAILS OF da; show sizes, weights, and all other impossive; set 3 join 106 REB surface. In casing to	WORK s, and lengths of proposed work ats 96.5' with 70 s	of 8-5/8" soks comes No pressur RE OIL CON Very before operations	OD 244
5-28-57 6-11-57	TD 106† REB. H-40 casing at circulated to Pressured up of in 30 minutes. this plan of work must receive to	DETAILS OF da; show sizes, weights, and all other impossive; set 3 join 106 REB surface. In casing to	WORK s, and lengths of proposed work ats 96.5' with 70 s	of 8-5/8" soks comes No pressur RE OIL CON Very before operations	decrease
5-28-57 6-11-57 I understand that	expected depths to objective sand ing point ing point ing point ing point ing point ing point in 100 minutes at circulated to in 30 minutes. This plan of work must receive this plan of work must receive the plan of	DETAILS OF da; show sizes, weights, and all other impossive; set 3 join 106 REB surface. In casing to	WORK s, and lengths of proposed work ats 96.5' with 70 s	of 8-5/8" soks comes No pressur RE OIL CON Very before operations	decrease