Form 3160-5 (August 1999)

UNITED STATES

FORM APPROVED

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						OMB NO. 1004-0135 Expires: November 30, 2000		
SUNDRY NOTICES AND REPORTS ON WELLS 3 4 5 Do not use this form for proposals to drill or to recenter an abandoned well. Use form 3160-3 (APD) for such proposals.					Lease Serial No. NMSF079296 If Indian, Allottee or Tribe Name			
								SUBMIT IN TRI
Type of Well				8. Well Name and No. BUTTRAM 3				
Name of Operator CONOCO INC	DEBORAH MARBERRY E-Mail: deborah.moore@usa.conoco.com			9. API Well No. 30-039-06426-00-C1				
3a. Address PO BOX 2197, DU 3084 HOUSTON, TX 77252-2197	3b. Phone No. (include area code) Ph: 281.293.1005 Fx: 281.293.5466			10. Field and Pool, or Exploratory BLANCO PC + Trt-Cool				
4. Location of Well (Footage, Sec., 7)			11. County or Parish, and State				
Sec 23 T26N R6W NENW 09 36.47690 N Lat, 107.44017 W				RIO ARRIBA COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE N	ATURE OF 1	NOTICE, RI	EPORT, OR	OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize	□ Deeper	ı	☐ Product	☐ Production (Start/Resume)		☐ Water Shut-Off	
_	☐ Alter Casing	☐ Fractur	re Treat		ition		■ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ New C	onstruction	☐ Recomp	lete		☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	🛭 Plug ar	☑ Plug and Abandon ☐ Tempor		arily Abando	n		
	☐ Convert to Injection	Convert to Injection		☐ Water D	Disposal			
13. Describe Proposed or Completed Oplif the proposal is to deepen direction. Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final At determined that the site is ready for f Conoco plugged and abandor 3/25/2002 Sam McFadden pro 3/26/2002 Sam McFadden pro anchors. Sam McFadden decito Lindrith B #24 instead. 4/1/2002 Jon Becksted projectines. Service rig. SDON. 4/2/2002 Safety mtg. RU equi	ally or recomplete horizontally, rk will be performed or provide to operations. If the operation recondoment Notices shall be fil inal inspection.) ned this well as per the folioject lead. Road rig and expect lead. Installed new of ided to move rig t lead. Road rig to loc. Spoment. Check pressures:	give subsurface loc the Bond No. on fis sults in a multiple c ed only after all req lowing: quipment. Drive triveline. Road ri ot equip. Too w SITP-100 psi. S	ations and meass le with BLM/BIA ompletion or reco uirements, including line broke. SE ig to loc. WO indy to rig up. SICP- 220 psi.	Lay flow Bled down Bled down Bled down Bled down Bled down Bled down Lay flow	rtical depths of osequent report new interval, a land, have been co	all pertine s shall be f Form 3160	nt markers and zones. iled within 30 days -4 shall be filed once	
WH. NU BOP's. Test BOPs w (total 3115'). TIH with tbg and out of CR. Load and circ hole Establish injection rate of 2.0 l	7" DHS cmt retainer. Set clean w/ 70 bbls water. P	CR @ 2888'. P' T csg to 500 psi	T tbg to 1000 i, OK. Sting in	psi, OK. Stir to CR.	ng T			
	# Electronic Submission For CO pmmitted to AFMSS for pro	NOCO INC, sent ocessing by Stev	to the Farming e Mason on 06	gton 5/03/2002 (025	SXM0234SE)			
Name (Printed/Typed) DEBORA	HMARBERRY	Т	itle SUBMI	TTING CON	TACT			
Signature (Electronic S	Submission)	D	ate 05/28/2	002				
	THIS SPACE FO	R FEDERAL	OR STATE	OFFICE US	SE			
Approved By ACC			PHEN MASC ROLEUM EN		Date 06	6/03/2002		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivinch would entitle the applicant to conduct the conduction of the		Office Farm	ington					

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #11558 that would not fit on the form

32. Additional remarks, continued

1.18 Cuft/sx.from 3166' to TOC @ 2338' (81 sxs squeezed and 106 sxs above CR as requested by R. Snow BLM). Sting out of CR. POOH to 1500'. Displace. LD tbg to 1500'. Load hole w/ 4 bbls water to circ. M&P Plug #2 as follows: 29 sxs cmt, from 1500' - 1350'. Displace. LD tbg. SIWON. 4/3/2002 Safety mtg & H2S training. Travel. Rig safety mtg. NO PRESS. RU A+ W/L. Perf with 3 HSC squeeze holes @ 147'. RD W/L. Pump 12 bbls water down csg and out bradenhead. CO while circ 18 bbls water. Mix & Pump Plug #3 as follows: 88 sxs type II cmt @ 15.6 ppg. Cmt circ out bradenhead. SI well. ND BOP's. Dig out and Cut-off wellhead. Place P&A marker. with 16 sxs Type II cmt. Cmt 30' in csg / Cmt 10' in 10 3/4" csg. RD Cut anchors. MO Loc. FRR. All Mt's 4/3/02.