

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Approved.
Bureau No. 42-21424.
DATE AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE
2. NAME OF OPERATOR Consolidated Oil & Gas Inc.	6. IF INDIAN ALLOTTEE OR TRIBE NAME Jicarilla Tribal
3. ADDRESS OF OPERATOR P.O. Box 2038, Farmington, New Mexico	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FSL & 1850' FEL, of section 16, Township 26 North Range 3 West, NMPM.	8. FARM OR LEASE NAME Apache
14. PERMIT NO.	9. WELL NO. 4-16
15. ELEVATIONS (Show whether OF, HT, OR, etc.) 7125 G.L.	10. FIELD AND POOL, OR WILDCAT Pictured Cliff & Bakota
	11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA Sec. 16, Twn 26 North, Range 3 West, NMPM.
	12. COUNTY OR PARISH Rio Arriba
	13. STATE New Mexico


Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All perforations squeezed prior to pulling pipe and plugging well. Used 35 sacks at top of 7" cut off stub at 1889'. Pulled pipe and dumped plug of 35 sacks at 306' - the 9 5/8" shoe. Put 10 sacks in top of 9 5/8" and around welded in marker. Cleaned and leveled location as required.



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Foreman

DATE 6-16-65

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

