UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	SF-079184
SUNDRY NOTICES AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Same
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 3160-3 for such proposals)	7. Unit Agreement Name
1. Oil Well [] Gas Well [] Other [] GAS WELL	BREECH "C"
2. Base of Operator:	3. Rell To. 389
Caulkins Oil Company	10. Field or Hildest Isse
3. Middless of Operator: (505) 632-1544 P.O. Box 340, Bloomfield, NM 87413	BASIN DAKOTA
4. Location of Hell (Report Location Clearly)	II. Sec. T.R.M. or Blk and Survey or Area
1650' F/S 1190' F/W	SEC. 13-26N-6W
14. API No.: Elevation (show NY, RT a	
300390647700-S1 6726	DF Rio Arriba NM
16. Intention To: Subsequent Report: Repaired Casing	
17. Bescribe Proposed or Completed Operations:	
3-30-93 Pulled tubing then set drillable plug on wireline at 6491'.	
3-31-93 Went in hole with tubing and packer to find casing leak. Found holes in casing at 1907' and another at 2395'. Ran Bond Log to determine cement top at 3300'.	
Shot 2 squeeze holes at 3295'. Set cement retainer at 3262'. Then cemented area between 3295' and hole in casing at 2395' with 200 sacks (236 cu. ft.) class "B" neat cement weighing 15.6 ppg.	
While pumping above cement job, circulation to surface through bradenhead was accomplished.	
bradenhead was accomplished. Pulled tubing then ran second cement retainer to 2333.	
Broke circulation through retainer at 2333' and Fole at 2395' to surface.	
Continued on reverse side.	
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5	
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT	
SIGNED: Robert L. Verquer TI	TLE: Superintendent DATE: 04/28/93
APPROVED BY: TITLE:	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY	MAY 0 5 1993 FARMINGTON DISTRICT OFFICE

Page 2 Breech "C" 389 April 27, 1993

4-1-93 Cemented 4 1/2" casing through hole at 2395' to surface with 325 sacks (721 cu. ft.) 50-50 Poz weighing 11.3 ppg. followed by 300 sacks (354 cu. ft.) class "B" neat cement weighing 15.6 ppg. Approximately 15 bbls. cement slurry circulated to surface.

4-2-93 Drilled out cement and cement retainers. thru Tested casing to 1500# held ok.

4-5-93 Drilled out bridge plug and cleaned out to 7620'.

4-6-93 Ran 2 3/8" tubing and landed at 7534'.
Well will be swabbed in, flowed to clean up and put back to sales line.