

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

5. Lease Designation and Serial No.

JIC CONT 110

6. If Indian, Allottee or Tribe Name

JICARILLA

7. If Unit or CA, Agreement Designation

ALBUQUERQUE N.M.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

WAYNE BRANAM

3. Address and Telephone No.

P.O. Box 800, Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1820FSL 1130FWL

Sec. 18 T 26N R 5W

8. Well Name and No.

JICARILLA A 1

9. API Well No.

3003906481

10. Field and Pool, or Exploratory Area

BLANCO (MESA VERDE)

11. County or Parish, State

RIO ARRIBA NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

AMOCO PRODUCTION COMPANY INTENDS TO PLUG AND ABANDON THE MESAVERDE FORMATION OF THIS DUAL COMPLETE WELL. THE OTHER FORMATION IS DAKOTA.

THE ABANDONMENT WILL BE PERFORMED PER THE ATTACHED PROCEDURES.

IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT ME AT (303) 830-4912.

RECEIVED
DEC - 6 1993
OIL CON. DIV.
DIST 3

14. I hereby certify that the foregoing is true and correct

Signed

Wayne Branam

Title

BUSINESS ANALYST

Date

11-11-1993

(This space for Federal or State office use)

(Original Signed) HECTOR A. VILLALOBOS

AREA MANAGER
RIO PUERCO RESOURCE AREA

Title

Date

DEC 2 1993

Approved by
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

Jicarilla A1
Basin Dakota/Blanco Mesa Verde
Sec 18L-T26N-05W
Packer Removal and PxA of Mesa Verde

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow well down. Kill, if necessary, w/ 2% KCl water. NDWH. NUBOP.
3. Unseat 2-3/8" tbg and sting out of Model N-1 PKR. Tbg has Model B seal assembly. Visually inspect tbg and replace any bad joints.
4. TIH w/ 5-1/2" bit and scraper to 7180'. (5-1/2" csg drift I.D. is 4.767") POOH.
5. RIH w/ 5-1/2" RBP. Set RBP at 5400'. TOOH.
6. TIH w/ cmt retainer. Set cmt retainer at 5100'.
7. Squeeze Mesa Verde formation. (See attached cement procedure) WOC.
8. TIH w/ 5-1/2" bit and scraper. Drill out cement. Pressure test casing. Circulate hole clean.
9. TIH. Release RBP. TOOH w/ RBP.
10. TIH and mill out Model N-1 PKR. POOH w/ PKR.
11. TIH and mill out Model D PKR. POOH w/ PKR.
12. TIH with mule shoe, 2-3/8" tubing, and seating nipple one joint off bottom. Clean out w/ N2 to PBTD. Land tbg at 7450'.
13. NDBOP. NUWH. RDMOSU. Return well to production, swab if necessary.

REPORT ANY PROBLEMS TO TY SMITH (socon 721-5164)

JICARILLA A 001 128
 Location - 18L- 26N- 5W
 SINGLE dk
 Orig.Completion - 11/61
 Last File Update - 1/89 by BCB

