Indian Agency J108F1118

2

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Allottee Jicarilla Triba
Lease No. Contract 109

SUNDRY NOTICES AND REPORTS ON WELLS

	TION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
	TION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
	TION TO TEST WATER SHUT-OFF	RECE
	TION TO REDRILL OR REPAIR WEL	
	TION TO SHOOT OR ACIDIZE TION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ABANDONMENT NOV 4-1958
	TION TO ABANDON WELL.	SUPPLEMENTARY WELL HISTORY. U. S. GEOLOGICAL SUP.
	TION TO ABANDON WELL	U. S. GEDEUGIOAL SEN
	(INDICATE ABOVE BY CH	HECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
		Oetober 30th 19.5
	-F is located 2055	ft. from $\{N\}$ line and 1470 ft. from $\{E\}$ line of sec. 15
(14 Sec. and) (Range) (Meridian)
GLAIATU (Fiel		(County or Subdivision) (State or Territory)
		ds; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, ceme ts, and all other important proposed work)
-18-58	TD 3311' REB. 3-55 casing at Temperature sur Pressured up on	ds; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, come ts, and all other important proposed work) Set 83 joints 3303' of 5-1/2' OD 15.5# 3310' with 100 sacks cement. Pvey showed top of cement at 2500'. A casing to 1000#. No pressure decrease
-18-58	TD 3311' REB. J-55 casing at Temperature sur	Set 83 joints 3303' of 5-1/2" OD 15.5# 3310' with 100 secks cement. Pvey showed top of cement at 2500'.
-18-58 -27-58	TO 3311' RED. 3-55 casing at Temperature sur Pressured up on in one hour.	Set 83 joints 3303' of 5-1/2 OD 15.5# 3310' with 100 sacks cement. rvey showed top of cement at 2500'. A casing to 1000#. No pressure decrease NOVE NOVE ON.
-18-58 -27-58	TO 3311' REB. 3-55 casing at Touperature sur Pressured up on in one hour.	Set 83 joints 3303' of 5-1/2 OD 15.5# 3310' with 100 sacks cement. rvey showed top of cement at 2500'. a casing to 1000#. No pressure decrease NOVE NOVE NOVE NOVE NOVE NOVE NOVE NOVE
1 understand that ompany	TO 3311' REB. 3-55 casing at Touperature sur Pressured up on in one hour.	Set 83 joints 3303' of 5-1/2 OD 15.5# 3310' with 100 sacks cement. rvey showed top of cement at 2500'. a casing to 1000#. No pressure decrease NOV ON. approval in writing by the Geological Survey before operations may be boing approach.
1 understand that ompany	TO 3311' REB. J-55 casing at Temperature sur Pressured up on in one hour. It this plan of work must receive a PASC NATURAL CA	Set 83 joints 3303' of 5-1/2 OD 15.5# 3310' with 100 sacks cement. rvey showed top of cement at 2500'. a casing to 1000#. No pressure decrease NOV ON. approval in writing by the Geological Survey before operations may be boing approach.

(Most