

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Contract #103

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla "H"

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Tapacito Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

**Sec. 18, T-26N, R-4W
N.M.P.M.**

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

1. OIL ☐ GAS ☒
WELL WELL OTHER

2. NAME OF OPERATOR

Southern Union Production Company

3. ADDRESS OF OPERATOR

P.O. Box 308, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650 Ft. from the North line and 1190 ft. from the East line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6713 G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Riggged up L & M Ventures pulling unit.
2. Ran 1-1/2" tbg. to 4860' and tag model "D" PKR
3. Pumped 15 sks cement 4860' to 4760'.
4. Pulled tubing to 3450', spot 40 sks cement plug 3450' to 3300'.
5. Pulled tbg. to 3100', pumped 27 sks cement plug 3100' to 3000'.
6. Pulled tbg. to 2000', pumped 27 sks cement plug 2000' to 1900'.
7. Pumped 5 sks cement plug down Braden head.
8. Pumped 10 sks cement plug @ surface.
9. Set dry hole marker and cleaned location.
10. Will reseed location in spring of 1977.

18. I hereby certify that the foregoing is true and correct

Original Signed by

SIGNED **James N. Bonaventura**
James N. Bonaventura

TITLE **Production Superintendent**

DATE **12/1/76**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side