

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. Contract 115
2. NAME OF OPERATOR Consolidated Oil & Gas Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Tribal
3. ADDRESS OF OPERATOR P.O. Box 2038, Farmington, New Mexico	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FSL & 790' FWL of Section 10 Township 26 North, Range 3 West, NMPM.	8. FARM OR LEASE NAME Jicarilla
14. PERMIT NO.	9. WELL NO. 1-10
15. ELEVATIONS (Show whether DF, HT, GR, etc.) 7063 G.L.	10. FIELD AND POOL, OR WILDCAT Pictured Cliffs & Mesaverde
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, Twn 26 North, Range 3 West, NMPM
	12. COUNTY OR PARISH Rio Arriba
	13. STATE New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Dumped 20 sacks or regular cement slurry on top of bridge plug at 5865'. Spotted 10 sacks cement across Pictured Cliff 3730 - 3802. Put 25 sacks regular cement 50' in 5 1/2" stub and 50' out of cut off stub at 2704'. Put 35 sacks at base of 8 5/8" shoe 320'. Put 10 sacks regular cement at top of 8 5/8" surface and around Marker. Erected and welded in appropriate marker. Clean and leveled location as required.

18. I hereby certify that the foregoing is true and correct

SIGNED *John L. Ward*

TITLE Production Foreman

DATE 6-16-65

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

\*See Instructions on Reverse Side

RECEIVED  
JUN 21 1965  
GEOLOGICAL SURVEY  
FARMINGTON, N.M.  
APPROVED  
JUL 20 1965  
John L. Ward  
ACTING DISTRICT ENGINEER