UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notic	es and Reports on	Wells
1. Type of Well GAS		 5. Lease Number Jic Apache Con #119 6. If Indian, All.or Tribe Name Jicarilla Apache 7. Unit Agreement Name
2. Operator Meridian Oil Inc.		8. Farm or Lease Name
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499		Jicarilla 119 N 9. Well No. 1
4. Location of Well 1650'S, 945'W		10.Field, Pool, Wildcat Tapacitos PC 11.Sec. T. R. M. or Blk Sec.08, T-26-N, R-04-W NMPM
14. Permit No.	15. Elevations 6806'GR	12.County 13. State Rio Arriba NM
16. Intent to/Subsequent Repor	rt of : Repair to	bing.
17. Describe proposed or compl	leted operations:	
A packer was set in this well testing, it was found that the will be pulled, bad joints of will be re-run. The well will economic.	tubing was plugg tubing removed ar be flow tested t	red. The tubing and packer ad the tubing and packer to determine if repair is R03 1990
18. Authorized by:	Affairs / Ermi	D(STS)3 1-22-90 Date
NOTE: This format is issued in	,	Form 3160-5
(This space for Federal or Sta	ate office use)	=======================================
APPROVED BY	TITLE	DATE
CONDITION OF APPROVAL, IF ANY	:	Approximately Action 1990 Ken Townsend
	× 5.	Chien, Escaro, es Mineral for an inves Fanningios Recosac o Area