Form	9-331 a
(Feb	. 1951)

l:			
1 1			
1			
1	:	i '	:

(SUBMIT IN TRIPLICATE)

Land	Office
Lease	No. 079161
Unit	

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NT REPORT OF SHOOTING OR ACIDIZINGNT REPORT OF ALTERING CASING
L L L L L L L L L L L L L L L L L L L
NT REPORT OF RE-DRILLING OR REPAIR
NT REPORT OF ABANDONMENT
NTARY WELL HISTORY
pe of Well Operator I
Ę

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			February 11,	, 19.63
Well No. 1 is located	1860 ft. 1	from $\begin{bmatrix} \mathbf{X} \\ \mathbf{S} \end{bmatrix}$ line a	nd 660 ft. from $\begin{bmatrix} E \\ \bullet \end{bmatrix}$ line of	sec 5
MR/A. SR.A. Sec. 6	26 N	7 ¥	n.m.P.	
12 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
So. Manco-PC (Field)	Rio Arr	unty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is .6162. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The operator of the above-mentioned well is Belin Oil Company, effective September 1, 1962, at 7:00 A.M.

I understand that this plan of work must receive approval in writing by the	Geological Survey before operations may be compressed
Company Bolin Gil Company	
Address 1120-011 & Gas Building	By B & 1967
Vichita Falls, Texas	By S COM
	Title
U. S. GOVERNMENT PRINTING OFFICE	16-8437-4