

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. Contract 115
2. NAME OF OPERATOR Consolidated Oil & Gas Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Tribal
3. ADDRESS OF OPERATOR P.O. Box 2038, Farmington, New Mexico	7. UNIT AGREEMENT NAME Jicarilla
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FWL & 990' FWL of Section 10, Township 26 North, Range 3 West, N.M.	8. FARM OR LEASE NAME Jicarilla
14. PERMIT NO.	9. WELL NO. 2-10
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Pictured Cliffs & Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10 Twp 26N. R 3 W. N.M.
	12. COUNTY OR PARISH Rio Arriba
	13. STATE New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☒	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Consolidated Oil & Gas Inc. proposes to plug and abandon the Jicarilla 2-10 as follows: Squeeze Dakota perforations from 7996 to 9206 and spot a cement plug across the Pictured Cliffs perforations from 3743 to 3804. A cement plug will be spotted across the stub of the 7" pipe at approximately 2000' with mud laden fluid between all plugs. A surface plug will be in the top 100' and a permanent marker erected. All pits will be leveled and the location cleaned of any junk.

This well is being plugged and abandoned because it is no longer an economical producer.



18. I hereby certify that the foregoing is true and correct

SIGNED

Thomas M. Egan

TITLE

Area Superintendent

DATE


2-3-65

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.