Form 3160-5 (August, 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

γĆ	DRM A1	PRC	νE	()
/ON	4B No.	1004	-01.	35
			30	2.1

c/	November	2/1	3000
Expires.	November	30.	2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No. SF-079162

·	0.0.02	
6. If Indian	Allottee or Tribe Name	

abandoned well. Use	Form 3160-3 (APD) fo	r such proposateவி	1 (F)			
SUBMIT IN TRIPLIC	ATE - Other Instructed	fision reverse fille	N SI	7. If Unit or C	A/Agreement, Name and/or No.	
I. Type of Well Oil Well X Gas Well	Other			8. Well Name		
2. Name of Operator		MKL 19 9. API Well No.				
LOUIS DREYFUS NATURAL GA	S CORP.	والمنطور والمرابية والمعافرة	Lune.			
3a. Address		3b. Phone No. (include	area code)	30-039-06621		
P.O. Box 370, Carlsbad, NM 882.	21	(505) 885-131	3	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			S. Blanco PC			
				11. County or	Parish, State	
990' FNL & 1650' FEL, UL B, Sec. 8,T-26N, R-7W			Rio Arriba, New Mexico			
12. CHECK APPROPRIATE	BOX(ES) TO INDICAT	TE NATURE OF NO	TICE, REPO	ORT OR OT	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Production (S	tart/Resume)	Water Shut-Off	
_	Attering Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		X Other	
	Change Plans	Plug and Abandon	Temporarily A	Abandon	Test water flow on Bradenhead	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	al		
13 Describe Proposed or Completed Oper	ation (clearly state all pertinent d	letails, including estimated	starting date of a	any proposed w	rork and approximate duration thereof. depths of all pertinent markers and zones.	

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

As per conversation of Mike Rainwater with Mr. Charles Perrin w/NMOCC, Louis Dreyfus Natural Gas Corp. will monitor well as follows:

- 1. Open bradenhead to atmosphere for one (1) hour and estimate the volume of water discharged while monitoring and recording casing pressure during flow period.
- 2. Shut-in bradenhead valve and monitor and record bradenhead and casing pressure for 15 minutes. Report results to BLM.

We will notify the Farmington office of the BLM 24 hrs prior to flow test.

HETER AZTED OCD 'N' T.ME TO WITNESS ____

14. I hereby cert Name (Printe	fy that the foregoing is true and correct 1 Typed)	1	
	→ Gene Simmer	Title	District Operations Manager
Signature	Sine Sime		1/26/2001
	THE APACO ROTHERDRING ON AFTER	p () and (co) (
Approved by		Title	Date 2/6/0
certify that the	pproval, if any, are attached. Approval of this notice does not warrant or applicant holds legal or equitable title to those rights in the subject lease	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.