

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

December 8, 1986

Mr. Ralph Montoya Amoco Production Co. 2325 East 30th Farmington, NM 87401

Re: Jicarilla Apache 102 #4 K-4-26N-4W

Dear Ralph:

Annual packer leakage test on the referenced was inconclusive in proving zone separation.

Please reschedule and retest the well in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere, or through the separator for as long as it takes to get a significant pressure drop.

Please advise this office at least 24 hours prior to test, so we may provide a witness.

Yours truly,

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Well File