Form 3160-5 (June 1990)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED			
Budget Bureau No. 1004-0135			
Expires: March 31, 1993			

	Expires:	March	31, 19	93
Lease	Designat	ion and	Serial	No.

6. If Indian, Allottee or Tribe Name

റ	7	9	1	6	റ	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

The remain and such proposals		
SUBMIT IN TRIPLICATE		
1. Type of Well Oil Gas Well Well Other		
2. Name of Operator		
Union Oil Company of California  3. Address and Telephone No.		
P.O. Box 2620, Casper, WY 82602, 307-234-1563  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		
1518' FXL, 980' FEL Sec. 1, T26N, R7W		
(s) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF ACTION		
Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)	
	alifornia  WY 82602, 307-234-1563  Description)  (S) TO INDICATE NATURE OF NOTICE,  TYPE OF A  Abandonment Recompletion Plugging Back Casing Repair Altering Casing	

3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drifted, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Union Oil Company of California (UNOCAL) intends to plug and abandon the Rincon well #47. See attached procedure.

MAROT 1994
OIL CON. DIV

SEE ATTACHED FOR CONDITIONS OF APPROVAL

SHEER IN PAY 2: 10

14. I hereby certify that the foregoing is true and correct		
Signed Im Denson	Title Drilling Superintendent January 27, 1994	
(This space for Federal or State of Calle) Benson Approved by	Title AP Bate ROVED	
Conditions of approval, if any:	MAR 01 1994	
	The second secon	==

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States and God, in the Control of t

TORREST OF CHARGE

Dist.	Prod.	Mgr.	
Dist.	Engine	eer	
Dist.	Drlg.S	Supt.	

### UNION OIL COMPANY OF CALIFORNIA ROCKY MOUNTAIN ASSET GROUP SOUTHERN ROCKIES AREA CONDITION OF HOLE & PROCEDURE

DATE: JANUARY 26, 1994

FIELD: RINCON AREA: FARMINGTON

LEASE/UNIT: RINCON WELL NO. 47

REASON FOR WORK: To plug and abandon Rincon Well #47.

CONDITION OF HOLE:

ETD or

TOTAL DEPTH: 2840' PBTD: 2840' KB DATUM IS: 7' ABOVE GL

CASING RECORD: 132' 9 5/8" 25.4# S.W. csg cmt'd w/ 125 sx

2772' 5 1/2" 15.5#, cmt'd w/ 150 sx

PERFORATIONS: Pictured Cliffs open hole - 2772-2840'

TUBING DETAIL: 2811' 134 jts 1" 1.68# 10rd tbg

ROD & PUMP

DETAIL: None


PROCEDURE:

c:\r47cndho.doc

# RINCON #47 PLUG & ABANDON PROCEDURE

- 1. Test deadmen. MIRU pulling unit w/ pump and tank. Kill well, if necessary. N.D. tree. N.U. BOP.
- 2. TOH and lay down prod. tbg and material transfer to Rincon Prod. yard. TIH w/ 4 3/4" bit on 2 7/8" tbg and tag ETD @  $\pm$  2840'. TOH.
- 3. TIH w/ 5 1/2" cmt retainer and set @ ± 2700'. Cement squeeze Pictured Cliff formation (2772-2840') w/ 50 sacks (Plug #1) Class "B" cement w/ 2% CaCl<sub>2</sub>. Sting out and spot 5 sx cement on top of retainer. POOH 60' displace wellbore w/ minimum 9.0 ppg, 50 viscosity bentonite based non-fermenting mud.
- 4. TOH w/ stinger to  $\pm 2260$ ', (50' below base of Ojo Alamo formation). Spot 20 sacks (Plug #2) same cement from  $\pm$  2260' to  $\pm 2160$ ' (Calc 100' min. w/ 50% excess). Displace w/ same mud. TOH.
- 5. Perforate 5 1/2" csg @ ±1830', 4 jspf (50' below top of Ojo Alamo formation). Perforate 5 1/2" csg at ±1690', 4 jspf (50' below top of Nacimiento formation).
- 6. TIH w/ 5 1/2" cement retainer and set @ ±1730' (100' above Ojo Alamo perfs). Spot and squeeze 5 1/2" csg w/ 65 sacks (Plug #3) same cement. Displace cement w/ same mud. Reverse circ. tbg clean leaving 5' of cmt on top of retainer. TOH.
- 7. TIH w/ 5 1/2" cement retainer and set @ ±1590' (100' above Nacimiento perfs). Spot and squeeze 5 1/2" csg w/ 65 sacks (Plug #4) same cement, leaving 5 sacks on top of retainer. TOH to 300'.
- 8. Pump and spot 40 sacks (Plug #5) from 300' to surface. TOH.
- 9. Cut off wellhead 3' below ground level and install dry hole marker. Clean up and restore location. Well P&A'd.

### **UNOCAL**®



#### UNITED STATES DEPARTMENT OF THE INTERIOR

# BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: FT Rincon Unit

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):

1.) Extend cement pluy spothed on top of retaine a

2700' to come up to 2484'. (Top of Fruithed 202534')

2.) Pluce a cement pluy from 2259' to 1943' inside the casing plus 50 Linear feet excess. (Oio Almo 1993'- 2209')

3.) Pertonte a 972', pluce a cement pluy from 972' to 872' Inside to stride the casing plus 1002 excess in the anythe & 50 Linear feet inside the casing (Naciminho-922')

4.) Pertonte a 182' and circulate cement to the Luchace.

(Surpre case 2132')

Office Hours: 7:45 a.m. to 4:30 p.m.

Note! It is not Necessary to parton to 2 1830' and 1690'.