

GOVERNOR
JACK M. CAMPBELL
CHAIRMAN

State of New Mexico
Oil Conservation Commission



LAND COMMISSIONER
E. S. JOHNNY WALKER
MEMBER

P. O. BOX 871
SANTA FE

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

January 8, 1964

Mr. Emery C. Arnold
Supervisor, District 3
Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Re: Consolidated Oil & Gas, Inc., NSL

Dear Emery:

We have received an application from Consolidated Oil & Gas, Inc., to drill a Mesaverde and Dakota dual at a non-standard location 1968 feet from the South line and 1286 feet from the West line of Section 5, Township 26 North, Range 4 West, NMPM, Rio Arriba County.

Will you please verify the topography at the proposed location. We will issue the NSL order upon receipt of your verification as there are no offset operators.

Very truly yours,

J. M. DURRETT, Jr.
Attorney

JMD/esr



OIL CONSERVATION COMMISSION
DISTRICT

OIL CONSERVATION COMMISSION
BOX 871
SANTA FE, NEW MEXICO

DATE 1-15-64

Re: Proposed NSP _____

Proposed NWU _____

Proposed NSL ✓ _____

Proposed NFO _____

Proposed DC _____

Gentlemen:


I have examined the application dated 1-8-64
for the Consolidated O & G Well Loc 1286 from W₂T₁ 168 ft. Sec 7
Operator Lease and Well No. S-T-R
Sec 5, 26 N 4 W

and my recommendations are as follows:

This location is new standard only with respect to
inner boundaries of the Unit & therefore no
offset approval is required approval is
recommended.

Yours very truly,

Emory C. Lewis



Consolidated Oil & Gas, Inc.

Executive Offices

SUITE 2112 TOWER BLDG.
DENVER-U. S. NATIONAL CENTER
1700 BROADWAY
DENVER 2, COLORADO
PHONE AMHERST 6-1306

December 30, 1963

Mr. A.L. Porter
Secretary Director
New Mexico Oil Conservation Commission
P.O. Box 871
Santa Fe, New Mexico

Dear Mr. Porter

Please find enclosed a plat showing the proposed non-standard location for a Mesaverde and Dakota dual well in Section 5 Township 26 North, Range 4 West. We have been designated operator for the entire section and therefore no waivers are required from off set operators.

The standard location 1590 from the south line 1595 from the west line is located in a narrow box canyon that is almost impossible to build access roads into and would constitute undue hazards for gas drilling.

We would like to request administrative approval for this non standard location due to the drilling hazards and difficult problems that would be encountered in building roads and a suitable location.

Respectfully submitted,

CONSOLIDATED OIL & GAS INC.

Thomas M. Boyd Jr.
Thomas M. Boyd Jr.
Area Superintendent

cc: Mr. Robert B. Tenison
Mr. Emry Arnold
file

