
Form	9-881 a
(Feb	. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa	ře.
	080312-	

		X	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLAN	vs		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER	SHUT-OFF	ļ	SUBSEQUENT REPORT OF ALTERING CASING.	
NOTICE OF INTENTION TO RE-DRILL OR	REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR AC	CIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALT	ER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WE	ш			
(INDICATE	ABOVE BY CHECK MARI	K NATU	RE OF REPORT, NOTICE, OR OTHER DATA)	
	June 10			, 19. 6 6
	1980 ft. from	7	line and 1986 ft. from W line of sec.	5
of Mi Section 3	26 # 1 #.		e) (Meridian)	
(1/2 Sec. and Sec. No.)	. (Twp.)	(Rang	e) (Meridian)	
Puerte Chiquita (Field)	(County	or Sub		
\$20×0	d.		ethen enterin	
he elevation of the	above sea le	vel i	s 7192 ft.	
	DETA	ILS	OF WORK	
tata a summer of and appeared depths to ob	inctive sends: show six		ights, and lengths of proposed casings; indicate mudding jo	hs. cemen
tate limites of milit expected deptile to on	ing points, and all	,		
		other i	mportant proposed work)	
Drill with cable tool has 9 5/8" casing and subsequently emalier to total depth. If p two stage counting to upper strings and con water to surface.		of r sh o st cous	the Greenhorn at 3000's. at off though Heesverde with	
hen 9 5/8° casing and subsequently emplies to total depth. If p two stage counting to upper strings and con water to surface.	dry hole caw dry hole caw reduction en- red. Coment unt through	of T sh e st even ave two	the Greenhorn at 3000's, at off through Heseverde with trings to \$ 1/2" as required stand run long string with and shoe of long string, pull stage tool from below Heseverth (IN14 MOIL COM)	
han 9 5/8° casing and subsequently emplies to total depth. If y two stage counting t upper strings and con water to surface.	dry hole saw endection en- scal. Commit- umt through	of T sh e st even ave two	the Greenhorn at 3000's, mt off through Heseverde with crings to 5 1/2" as required stated run long string with and shoe of long string, pull-stage tool from below its application. UN14 MOIL COM.	

GPO 862040

