DIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

July 18, 1962

Standard Oil Company of Texas
Division of California Oil Company
Drawer "St
Monahans Texas

Attn: Mr J D.Rowland

Re: Intex 5 #1, H-5-26N-1E

Puerto Chiquito-Gallup Pool

Dear Mr. Rowland:

Miscellaneous Notice indicates $4\frac{1}{2}$ casing has been run in subject well without cement. Rule 107 of our Rules and Regulations requires all casing to be cemented.

Please cause cement to be placed behind the $4\frac{1}{2}$ casing as required by Rule 107 or secure exception to the cementing requirement.

Yours very truly

ARK: ks

A. R. Kendrick Engineer District #3

DIE OFWEER? FON COMMISSION TOUGH STEARED STORY

ARTED, MEW MENICO

estropia (j. 1913.) i i i indotes Colo Din interior de l'Origina este t Autoritatione Company of the Company

Control of the transfer of the second of the

Areton-Telling in 1981 and 1981 Since the Franciscope of the 1982

్ ప్రావారం కాట్లో మూర్ మార్క్ ముద్దారు. ముద్దారు కాట్లో ముద్దారు. మార్క్ ప్రావారం కాట్లో మార్క్ ప్రావారం ప్రావ ముద్దారు. ముద్దారు కాట్లో ముద్దారు. ముద్దారు ముద్దారు. ముద్దారు. ముద్దారు. ముద్దారు. ముద్దారు ముద్దారు. ముద్దా Casta 6. au 66 or 1 old

ිනා වේ........................මට්ට්රියේ මෙම ජීතික් මෙම සම්බන්ධ සිටියේ දිනා සම්බන්ධ සම්බන්ධ සිටියේ සිටියේ සම්බන් විශාවට සහ සම්බන්ධ කිරීමට සහ සම්බන්ධ සම්බන්ධ ස

1 " 1 " 5 Tall 1

the the total and sale Service of the service of