OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

January 29, 1964

Consolidated Oil & Gas, Inc. 4150 East Mexico Avenue Denver, Colorado

Attn: Mr. Robert B. Tenison

Re: Deviation Survey of the #1-5 Hoyt Located 1720* from the North line and 850' from the East Line, Section 5-26N-4W, Rio Arriba County, N.M.

Dear Mr. Tenison:

The deviation survey tabulation for the above well has been received in this office. We have calculated the total drift to be 445.5'. The closest lease line from the surface location is 850'; therefore if all the drift is assumed to be in the direction of the nearest boundary line the bottom of the hole would be located 404.5' from the drilling tract boundary.

We therefore consider this to be a legal location and will not require that a directional survey be conducted.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA: ks

OIL CONSERVATION COMMISSION

COURTIC CRAZES RUAD AZTEC, NEW MEXICO

A Committee of the comm

ර 1999 වේ රායක්ෂණ විසින් ණී වනුදා විශාවය. වෙද්දිල විසියේ විසියේ රෙන වෙනවෙයට ණම් රායක්ෂණ වියර්තනයට

... 1 Who Bolers is Ide is on

ilg services survey tabusition see about the see above the second of the

is consigned consistent that z=z has a single location of z=z+1 and z=z+1 and z=z+1 in z=z+1 . Since z=z+1 is the z=z+1

agian in a sectoria

ament Octobrilla Signature octobrilla

25 A VIZ

1726/N jec 5-26N.4W

Consolidated Oil & Gas, Inc.

Farmington, New Mexico

			January 23, 1964 (Date)	
TABULATION OF DEVIATIONS ON Hoyt # 1-5 (Well Name) Basin Dakota		/1- 5- 26 4 (Location)		
	DBSIL	(Pool)		
DEPTH	DEVIATION	DEPTH		DEVIATION
360 765 1535 2070 2393 2780 3224 3668 4148 4621 5050 5960	26 C 1/20 2./ 400 1 1/40 2.7 834 10 /42 235 1/2 42 290 2 3/4 /2.7 090 1 1/2 437 090 2 3/4 /2.7 090 2 3/	7906 8025 8148 8249 8270	20 21 190 22 190 21 125 14 100 14 20 21 20 21	+ 3 9 2
SIGNED J	r 1/-	, and seems		ng Contractor
STATE OF NET COUNTY OF S	(of James Ale	T. H.	, 19 6∮ , by