

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30039671702 D1
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-291-17
7. Lease Name or Unit Agreement Name State "A"
8. Well No. 62
9. Pool name or Wildcat Blanco MV - Basin Dakota
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6656 GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Caulkins Oil Company
3. Address of Operator P.O. Box 340 Bloomfield, New Mexico 87413
4. Well Location Unit Letter <u>A</u> : <u>1190</u> Feet From The <u>North</u> Line and <u>1190</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>26 North</u> Range <u>6 West</u> NMPM Rio Arriba County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Pull Plugged Tubing</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-3-92

Production from this well has decreased and will not  
unload fluid thru tubing. Barium Sulfate build up on  
bottom of production tubing is suspected.

We now propose to pull tubing to determine problems and  
then repair as necessary.

Estimated starting date September 10, 1992.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert L. Verquer TITLE Foreman DATE 8-3-92  
TYPE OR PRINT NAME Robert L. Verquer TELEPHONE NO. 505-632-1544

(This space for State Use)

Original Signed by CHARLES GHOLSON

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 05 1992

CONDITIONS OF APPROVAL, IF ANY: