Mr. A. L. Porter April 5, 1960 Page Two

- 1. Additional time is essential to evaluate the fractured shale reservoir.
- 2. It is Intex Oil Company's desire to keep the hole size sufficiently large to enable deepening with cable tools if production from the fractured shale indicates such deepening to be desirable.
- 3. Effectiveness of the WSO is evidenced by the production of clean pipe line oil.

4. Corrective measures would be undertaken immediately by Intex 0:1 Company should production or any other circulation indicate a water entry into the well bore.

Very truly yours

INTEX DIL COMPANY

R. B. Miller Production/Manager

RBM\gj

cc: Mr. Emery C. Arnold

uses, Larnington

Bob Peterson - Denver Office

YEARHOO HE CEINE

September 1997 1992 Transport 1997 Transport 1997

na programa de la composição de la composiç Composição de la composiç

ျခင္းကုန္မရာသည္။ ရည္ေတြ ျခင္းသမားသည္။ လုိ လုိသြားျမည့္ လုံသည္ စစ္မွားမွားမျခင္းလုိနီသည္။ လု နေနာက္သည္ စက္ခ်စ္ျမားများ

The Common of th

Town as Area of the second of

e de la companya della companya de la companya de la companya della companya della companya de la companya della companya dell