

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office State Fe
Lease No. 079160
Unit Rincon Belt

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 57 is located 990 ft. from N line and 990 ft. from E line of sec. 1
SW 1/4 Sec. 1 (1/4 Sec. and Sec. No.) 24N (Twp.) 7E (Range) 24N (Meridian)
South Dakota (State) Picayune (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6600 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Following the sand-water free on the subject well, which was reported on Sundry Notice dated November 21, 1957, it was not possible to flow the well continuously because it froze down the tubing. On April 9, 1958, a 10/16" choke was run and set at 7325 RSL. Since running the bottom hole choke, the well has shown no signs of freezing. On a 5 day average, the well made 516 MCF/D and 19 barrels of distillate per day.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXAS NATIONAL PETROLEUM CO.Address 1054 W. BroadwayFarmington, New Mexico

By

D. E. A. Johnson

Title

D. E. A. Johnson
General Manager
Four Corners Area