1. ol

well

2. NAME OF OPERATOR DEPCO, Inc. 3. ADDRESS OF OPERATOR

AT SURFACE:

AT TOTAL DEPTH:

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOCT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\*

REPORT, OR OTHER DATA

gas

well

AT TOP PROD. INTERVAL: Same

(other) Request for Temp. Aban Status

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

1025 Petroleum Club Bldg.-Denver, CO 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 990 FNL, 990 FEL Sec. 5-26N-7W

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.

UNITED STATES ARTMENT OF THE INTERIOR	5. LEASE SF-079162
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
TICES AND REPORTS ON WELLS r proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
1-C for such proposals.)	8. FARM OR LE <b>ASE NAM</b> E MKL
other Shut in.	9. WELL NO.
ATOR	<b>/4-</b> 15
•	10. FIELD OR WILDCAT NAME
PERATOR	Blanco So P.C.
<pre>leum Club BldgDenver, CO</pre>	11. SEC., T., R., Mª OR BLK. AND SURVEY OR
FNL, 990' FEL Sec. 5-26N-7W	AREA Sec. 5-T26N-R7W
INTERVAL: Same	12. COUNTY OR PARISH 13. STATE Rio Arriba NM
H: Same	14. API NO.
PRIATE BOX TO INDICATE NATURE OF NOTICE,	
THER DATA	15. ELEVATIONS (\$HOW DF, KDB, AND WD)
TOWN TO SUPERIOR PEROPE OF	6637' GR
ROVAL TO: SUBSEQUENT REPORT OF:	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)-

N

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

EL 4-15 has not sold any gas since May, 1971, when the well died. roduction had been approximately 1000 MCF/Mo. In July, 1971, the well was cleaned out to bottom and swabbed in an attempt to restore 2.15 2.15 2.19 2.98 3.4 The effort was unsuccessful. production.

DEPCO, Inc. requests approval to extend the temporary-abandoned tatus of the MKL No. 4-15 pending future gas price increases sufficient o warrant a recompletion attempt on this well.

le foregoing is true and correct TITLE Dist. Prod. Suptate May (This space for Federal or State office use) ★ÓVED BY TITLE CONLITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

nt