


(SUBMIT IN TRIPLICATE)

Indian Agency JicarillaUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. Tribal 101

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	RECEIVED SEP 3 1963 U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS	☐	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	☐	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	☐	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	☐	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	☐	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	☐		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 30, 1963

Huron
Well No. 2-2 is located 990 ft. from N line and 890 ft. from W line of sec. 2

NE/4, Section 2 26N 4W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin Dakota Rio Arriba New Mexico
Tapcito Pictured Cliffs (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6964 ft. KB
6952 GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Drill 15" hole to 300', run 13 3/8" surface casing, cement to surface with 300 sx. Drill 11" hole to 4000' with mud, run 8 5/8" intermediate casing, cement with 300 sx. Gas drill 7 7/8" hole to TD of approximately 8300'. Run 5 1/2" liner from 3900' to 8300', cement with 400 sx. Perforate Dakota and Pictured Cliffs and selectively sand-water frac and effect approved type dual completions with packer and two tubing strings.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Huron Drilling Company, Inc.

Address 715 Farmers Union Building
Denver 3, Colorado

By [Signature]
 Title President

August 30, 1963

HURON DRILLING COMPANY, INC.

Huron

26 HOBAN

11211

EST

~~160~~ 160.80

Pictured Cliffs

Tapicito

X



RECEIVED

SEP 3 1963


U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Huron Drilling Company, Inc.

[Signature]

715 Farmers Union Building

Denver 3, Colorado



Ref: GLO plat A-100, Nov. 1882

Scale: 1 inch equal 1 mile

This map was prepared from field notes of actual surveys made by the U.S. Geological Survey and is true and correct to the best of our knowledge and belief.

23 August 1963

[Signature]
Professional Engineer and Land Surveyor
Frank P. Leese, N. Mex. Reg. No. 1463

CONSOLIDATED OIL & GAS, INC.

3-25-68

WELLS REQUIRING FILE CORRECTION ONLY

LEASE NAME & WELL NUMBER	LOCATION	POOL	PRESENT ACREAGE	CORRECT ACREAGE
Ladd #1	C-19-25N-9W	Basin Dak.	N 320	N 321.80 ✓
Mills #1	K-19-25N-9W	Basin Dak.	S 320	S 321.40 ✓
Huerfano #1	A-30-25N-9W	Basin Dak.	N 320	N 321.14 ✓
Navajo #1	A-2-25N-10W	Basin Dak.	E 320	E 319.79 ✓
Huron #3	A-2-26N-4W	Tapacito PC	160	160.58 ✓
Huron #3	A-2-26N-4W	Blanco MV	E 320	E 320.58 ✓
Huron #2	D-2-26N-4W	Tapacito PC	160	160.80 ✓
Huron #2	D-2-26N-4W	Basin Dak.	W 320	W 320.80 ✓
Huron #1	M-2-26N-4W	Blanco MV	W 320	W 320.80 ✓
Huron #4	P-2-26N-4W	Basin Dak.	E 320	E 320.58 ✓
Linda #1	M-31-27N-8W	Blanco MV.	W 320	W 322.40 ✓
Rourke #1	M-4-30N-13W	Basin Dak.	W 320	W 320.20 ✓
Mitchell #1	N-5-31N-12W	Basin Dak.	W 320	W 318.36 ✓
Southern Union #2	A-19-31N-12W	Basin Dak.	N 320	N 318.24 ✓
XXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXX		XXXXXX	XXXXXX
Hancock #1	A-1-31N-13W	Blanco MV	N 317.78	N 319.20 ✓
Chavez Com #1	A-2-31N-13W	Blanco MV	E 320	E 319.40 ✓
Alberding #1	A-3-31N-13W	Blanco MV	E 319.03	E 320.10 ✓
Landauer #1	H-3-31N-13W	Basin Dak.	E 319.03	E 320.10 ✓
O'Shea #1	K-3-31N-13W	Blanco MV	W 319.92	W 320.30 ✓
O'Shea #1	K-3-31N-13W	Basin Dak.	W 319.92	W 320.30 ✓
Baird #1	H-4-31N-13W	Blanco MV	E 320	E 320.90 ✓
Baird #1	H-4-31N-13W	Basin Dak.	E 320	E 320.90 ✓