(A)	1. (32)	~	
0			
	2		
			- 1
,			1

(SUDMIT IN TRIPLICATE)

UNITED STAYES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency Jicarilla
••••••••••••••••••••••••••••••••••••••
Allottee Tribal 101
Loase No.

GEOL	ogical survey	Loase No.		
L. in its and				
SUNDRY NOTICES .	and reports	ON WELLS		
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF	WATER SHUT-OFF	X	
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF	SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	·	SUBSEQUENT REPORT OF ALTERING CASING.		
MOTICE OF INTENTION TO REDRILL OR REPAIR WELL.	i II	SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENTSUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL H	SUPPLEMENTARY WELL HISTORY.		
NOTICE OF INTENTION TO ABANDON WELL				
(IND:CATE ABOVE BY CHECK MAR	K nature of report, notice, o	ROTHER DATA)		
	Nove	mber 8	19.63	
Huron		~~		
Well No. 2-2 is located 990 ft. f	rom [N] line and 890	ft from [X] line of a	CELLA	
Weii 1.0	10111 [X] 11110 and		FITTUEN \	
NW 2 26N	4W NMF		TOTIATO	
()4 sec. and sec. No.) (Twp.)		widian)	JOV1 9 1069	
	Arriba		NOV1 3 1963	
Tapacito Pictured Cliffs (Coun	ty or Subdivision)	(State or Torrit Ty)	L CON. COM.	
The elevation of the derrick floor above sea!	evel is 6964 ft. KB		DIST. 3	
	6952 G L			
DETA	ails of Work			
(State name, of and expected depths to objective sands; show ing points, and al	sizes, weights, and lengths of prop	osed casings; indicate mudding	jobs, cement-	
ang prosecuj ana a		•		
Drilled 7-7/8" hole to 8160'. Ran	5-1/2" casing as	liner, set at 8167	'' KB,	
top of liner at 3863' KB, cemented				
and 2% CaCl ₂ and 10 sx. of regula	r with 4% CaCl2.	Plug down at 10:	00 A.M.,	
10/5/63. On 10/18/63, cleaned or	ut to top of liner,	tested top of line:	to.	
3000 psi, held okay.			5	
5000 psi, neia em,		DEGE		
		NOV.	13 1 883	
	y.	MOA	1,7 1000	
·			WOM Shire IY	
		U. S. CECLUI	MCAL SURGEY	
I understand that this plan of work must receive approval	in writing by the Geological Surv	rey before operations may be c	ommonced.	
		•		
Company Huron Drilling Co	mpany, Inc.			
715	4		1	
Address Suite 715	7	34×2	/	
1575 Sherman Street	By T		The -	
	- ' ' ' ' ' ' ' '			
Denver, Colorado 80203	_ Title	President		
			, .	
U. S. GOVERNA	ENT PRINTING OFFICE 16-8437b-8			