

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Jicarilla

Allottee Tribal 101

Lease No. _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

		0
2		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Change of Operator	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 28, 1964

Huron
Well No. 3-2 is located 975 ft. from [N] line and 810 ft. from [E] line of sec. 2.

NE 2
(¼ Sec. and Sec. No.)26N
(Twp.)4W
(Range)NMPM
(Meridian)Blanco Mesaverde
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)

Tapacito Pictured Cliffs

The elevation of the derrick floor above sea level is 7245 ft. KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per attached Designation of Operator, the Huron No. 3-2 well formerly operated by Huron Drilling Company, Inc. will now be operated by Consolidated Oil & Gas, Inc.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Consolidated Oil & Gas, Inc.

Address 4150 East Mexico Avenue

Denver 22, Colorado

By W. D. Williams

Title Chief Engineer

