

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Marathon Oil Company

3a. Address  
PO Box 2490 Hobbs, NM 88240

3b. Phone No. (include area code)  
505 / 393-7106

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
UL M, Sec. 28, T-26-N, R-5-W  
1040' FSL & 800' FWL

5. Lease Serial No.  
Tract 251 Contract 154

6. If Indian, Allottee or Tribe Name  
Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.  
Jicarilla Apache No. 11

9. API Well No.  
30-039-08149

10. Field and Pool, or Exploratory Area  
PC / BD

11. County or Parish, State  
Rio Arriba NM

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

**TYPE OF ACTION**

- |   |   |  |  |
|---|---|--|--|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off              |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity              |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input checked="" type="checkbox"/> Recomplete     | <input checked="" type="checkbox"/> Other <u>DHC</u> |
| <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |  |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |  |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

- 8/12 RU pulling unit. ND wellhead. NU BOP. POOH w/short string. Parted long string while trying to release it. RIH w/overshot. Backed off long string at safety jt (6939') & POOH. RIH w/RBP & pkr. Set RBP at 5312', pkr at 5280'. Test. Dump sand on RBP. POOH w/pkr. RIH w/4 1/2" csg & pkr to top of 4 1/2" liner. Set pkr.
- 8/25 Run GR/CBL/CCL log from PBTD-3000'. Perf csg for sqz holes at 3615', 3850', 4560', 5180', 4 holes each. Sqz w/285 sks Class B Cmt. DO cmt to RBP at 5312'. Rel. POOH w/RBP. Drill on pkr. Unable to retrieve pkr.
- 9/10 RIH w/RBP & pkr. Set RBP at 5260', pkr at 5130'. Test sqz holes to 2000 psi, OK. Rel. POOH w/pkr. Perf Mesa Verde 4808-5126' w/1 SPF, 25 holes. RIH w/RBP & pkr, set at 5158' & 4722'. Acidize w/1000 gals 15%HCL acid. Rel pkr & RBP. POOH. Frac w/116,388 gals frac fluid containing 115,000# sand. RIH w/RBP, set at 3810'.
- 9/12 Perf Chacra 3714-3739' w/2 SPF, 50 holes. Acidize w/1000 gals 10% acid. Frac w/12,587 gals 70Q N2 containing 65,000# sand. Open well to test. RIH, tag sand. Clean out to RPB at 3810', rel. POOH. RIH, tag sand at 5094'. Clean out to 5163' (RPB at 5260'). POOH.
- 9/22 RIH w/2 3/8" tbg. Land tbg at 4145'. ND BOP. NU wellhead. RD pulling unit. Currently testing Chacra & Mesa Verde. RBP at 5260'. PC is produced between the 4 1/2" liner & csg.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)  
Kelly Cook

Title

Admin. Assistant

Date August 31, 2001

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

SEP 27 2001

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office