Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources District I Revised March 25, 1999 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II 30-039-08180 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 88210 5. Indicate Type of Lease District III 2040 South Pacheco Jicarilla 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 FED. Lease No. NM041 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PROPOSALS TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR DEPARTS (CONTRACTOR) Lease Name or Unit Agreement DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) OR SUCH East Puerto Chiquito Mancos Unit PROPOSALS.) 1. Type of Well: Oil Well 23 Gas Well Other Water Injection Name of Operator CH. DIV 8... Well No. Benson-Montin-Greer Drilling Corp. **EPCMU #24 (F-6)** Address of Operator Pool name or Wildcat 4900 College Blvd., Farmington NM 87402 **East Puerto Chiquito Mancos** Well Location Unit Letter F : 2,400' feet from the FNL line and 1990' feet from the __FWL___line Township 26N Section 6 Range 1E NMPM County Rio Arriba County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 7,319' (RKB) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** ☐ CHANGE PLANS COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: X (Repair Tubing/Packer Leak) OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Estimate work to begin the on or after June 13, 2001 NOTIFY AZTEC OCD 1. MIRU WSU. NUBOP. IN TIME TO WITNESS 2. POOH w/ Injection Tubing and Packer. Redress and rerun Packer and Tubing. 3. 4. Load Casing-Tubing Annulus and pressure test to 300 PSIG for 30 minutes. NDBOP. Flange up wellhead.RDMO WSU. 5. Contact NMOCD with 48 hours notice. Chart and record UIC MIT (300 psig 30 minutes - no more than 10% fall-off) See Attached well bore diagram. KMAX 96 minuse Clock 1000 # SPRing I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Petroleum Engineer DATE 6/12/01 Type or print name Patricio W. Sanchez Telephone No. 505-325-8874 (This space from MAIS CISAND BY CHARLE T. PERSON

TITLE

DATE _____ DATE



Conditions of approval, if any:

APPPROVED BY