

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <u>Dual</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>Jicarilla Cont 110</u>
2. NAME OF OPERATOR <u>Tenneco Oil Company</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME <u>Jicarilla, Dulce, N. M.</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 1714, Durango, Colorado</u>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1750' FNL 1450 FEL</u>		8. FARM OR LEASE NAME <u>Jicarilla "A"</u>
14. PERMIT NO.		9. WELL NO. <u>#5</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6630 GR</u>		10. FIELD AND POOL, OR WILDCAT <u>Undes. Gallup & Bawin Dakota</u>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 20 T26N. R5W</u>
		12. COUNTY OR PARISH <u>Rio Arriba New Mexico</u>
		13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒


(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up completion rig 11/28/65. Cleaned out to 7555. Tested casing to 4000 lbs OK. Perf 7497-7273. Spotted 350 gallons acid and 1250 gallons mud acid. Frac perfs w/75,000 lbs sand and 85,000 gallons water. Perf 6756-6780 w/2 HPF. Frac w/60,000 lbssand and 55,000 gallons water. Cleaned out to 7555. Set Production packers at 7250. Ran 2-1/16" tubing landed in packer at 7250. Installed Kmas tree. Job complete 12/10/65. Well SI



18. I hereby certify that the foregoing is true and correct

SIGNED Harold C. NicholsTITLE Senior Production ClerkDATE 12/20/65

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

Distribution: 5 to USGS in Farmington, 1 to Continental, 1 to File

*See Instructions on Reverse Side