

2 FC 3e (4) file  
Louis Dreyfus Natural Gas Corp.

Quail Springs Corporate Park  
14000 Quail Springs Parkway, Suite 200  
Oklahoma City, OK 73154  
(405) 344-1300

October 30, 1995

Oil Conservation Division  
1000 Rio Brazos Road  
Aztec, NM 87410  
Attn: Frank Chavez

RECEIVED  
NOV - 1 1995

OIL CON. DIV.  
DIST. 3

Mr. Chavez,

This memo is in response to your certified letter concerning MKL #4 located at 990 FNL/1650' FEL in section 6-34-20N, R-7W, Federal lease SF079162.

After consultations with Mr. Joe Kaime and others familiar with the Largo wash, LDNG has devised a plan of action to reclaim the eroded location on MKL #4.

The plan consists of three fences upstream of the well site. These fences will be built with 5 1/2" casing posts which will be drilled in to approx. sixteen feet into the wash. The posts will be set ten feet apart with a heavy gauge V mesh wire attached to them.

The fences will not block the flow of the wash, but is designed to turn the flow away from the well pad. A sketch of the plan is attached.

At the same time the fences are built, we will also set 5 1/2" casing posts around the exposed wellhead and casing at MKL #4. The post will be drilled to 16 to 25 feet deep and be tied together with a top rail and heavy gauge wire. This action will prevent damage to the well casing.

After such time when we are successful in re-directing the flow away from this well the well location will be rebuilt.

If you need any further assistance concerning this matter, please feel free to contact me at my office at (505) 326-6958.

Sincerely,



Gene Simer  
Production Foreman



KARAO WASH

MKT #4



200'

150'

75'