

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or to test or to develop a well or to develop a reserve.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

OCT 07 1985

|  |  |  |  |   |  |                        |  |                  |   |  |                                    |                         |
|--|--|--|--|---|--|------------------------|--|------------------|---|--|------------------------------------|-------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | 2. NAME OF OPERATOR<br>Southland Royalty Company           | 3. ADDRESS OF OPERATOR<br>P. O. Drawer 570, Farmington, New Mexico 87499 | 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface (A) 1100' FNL & 990' FEL | 5. LEASE DESIGNATION AND SERIAL NO.<br>Jicarilla Contract 101 | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME<br>Jicarilla Apache Tribe | 7. UNIT AGREEMENT NAME | 8. FARM OR LEASE NAME<br>Jicarilla 101 | 9. WELL NO.<br>1 | 10. FIELD AND POOL, OR WILDCAT<br>Tapacito PC/Blanco MV | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Section 1, T26N, R4W | 12. COUNTY OR PARISH<br>Rio Arriba | 13. STATE<br>New Mexico |
| 14. PERMIT NO.   | 15. ELEVATIONS (Show whether DF, RT, OR, etc.)<br>7185' GL |  |  |   |  |                        |  |                  |   |  |                                    |                         |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

|  |   |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETION <input type="checkbox"/>  |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input type="checkbox"/>             |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         |
| (Other) <input type="checkbox"/>             |   |

SUBSEQUENT REPORT OF:

|  |  |
|--|--|
| WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>          |
| FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/>         |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input checked="" type="checkbox"/> |
| (Other) <input type="checkbox"/>               |  |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-18-85 to 10-01-85

MIRU Completion Rig on 9-18-85. Installed BOP. TOOH with dual production string. TIH with 2-3/8" tbg. Milled out Model "D" pkr @ 5640'. TIH with 3-7/8" and 4-1/2" casing scraper. Mill stuck @ 6013'. Chemical cut at 5971'. TIH with washover pipe assembly. Washed over fish at 6013'. TOOH. TIH with overshot assembly. Tbg parted, rec 24' of 2-3/8" tbg. TIH with 3-7/8" junk mill. Dressed top of fish by milling 30". TIH with overshot assembly, could not catch fish. TOOH. TIH with mill shoe and wash pipe assembly. Milled 6" to dress top of fish. TOOH. TIH with mill shoe and wash pipe assembly. Washed over 18". TOOH. Left mill shoe in hole. TIH with 4-1/2" RTTS pkr and set at 4200'. Established rate into Mesaverde perfs at 4 BPM with 1400 psi. TOOH. TIH with 4-1/2" E-Z drill cement retainer amd set at 5594'. Pressure tested tubing to 3000#.

10-02-85

Squeezed with 105 sacks (123.9 cu.ft.) of Class "B" cement. Final pressure 2400 psi. Stung out of E-Z drill, left 5 sacks of cement above retainer. POOH. LD 70 jts of 2-3/8" tbg. Landed 128 jts (3988') of 2-3/8", 4.7#, J-55 Pictured Cliffs tbg at 3998'. ND BOP and NU WH. Rel rig at 5:00 PM 10-02-85. Plugged and abandoned Mesaverde formation on 10-02-85. Pictured Cliffs formation shut in.

18. I hereby certify that the foregoing is true and correct

SIGNED Ester J. Greyer

TITLE Secretary

DATE 10-04-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 15 1985

OCT 11 1985

FARMINGTON RESOURCE AREA

BY Smn

\*See Instructions on Reverse Side