

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR
Supron Energy Corporation

3. ADDRESS OF OPERATOR
P. O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: **1850'/South & 790'/East line.**
AT TOP PROD. INTERVAL: **Same as above.**
AT TOTAL DEPTH: **Same as above.**

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF ☐ ☐
FRACTURE TREAT ☐ ☐
SHOOT OR ACIDIZE ☐ ☐
REPAIR WELL ☐ ☐
PULL OR ALTER CASING ☐ ☐
MULTIPLE COMPLETE ☐ ☐
CHANGE ZONES ☐ ☐
ABANDON* ☐ ☐
(other) **Comingle Dakota-Gallup/Dual w/Pictured Cliffs.**

5. LEASE **Contract No. 153**
6. IF INDIAN, ALLOTTEE OR TRIBE NAME **Jicarilla Apache**
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME **Jicarilla "J"**
9. WELL NO. **10**
10. FIELD OR WILDCAT NAME **Basin Dakota -Gallup/Pictured Cliffs**
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA **Sec. 26, T-26N, R-5W, N.M.F.M.**
12. COUNTY OR PARISH **Rio Arriba** 13. STATE **New Mexico**
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) **6627 KB**

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Comingle Order Number R-5858.

1. Move on location and rig up. Pull Gallup tubing string, 1-1/2", 2.76#, I.J.
2. Pull Dakota string if possible - if not, cut off at approx. 7000 ft. (Packer at 7090') & pull 1-1/2" 2.9# E.U.E.
3. Set Retrivable Bridge Plug at 3200' and free Pictured Cliffs formation from 3055' to 3113'. Clean up well and pull Retrivable Bridge plug.
4. Run 1-1/2" EUE tubing with Model "R" production packer and set at approx. 6650 ft.
5. Run 1-1/2" I.J. tubing to approx. 3050 ft.

Formation Tops: Pictured Cliffs - 3050'.
Gallup (Tecito) - 6718'.
Dakota - 7252'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED **O. B. Whittemburg** TITLE **Area Engineer** DATE **June 6, 1979**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount; size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.