IMORD HOTEC.	n Long to the control of the control				1				
File.	in the second section	_	•	ER-LEAKAGE TEST	/ Well	A			
Operator	JEROME P.	Mª Hugh	Le	ase <u>APACH</u>					
of Well:	Unit L Sec. /	8 Twp. 24	Rge Type of Prod.	• 3W Method of P	County Rio Arri	dium			
	Name of Reser	rvoir or Pool	(Oil or Gas)	(Flow or Art.	Lift) (Tbg. or (Csg.)			
Upper Completion	GAILUP		GAS GAS			_			
Lowe r Completion	DAKOTA			Flow	T69	-			
· · · · · · · · · · · · · · · · · · ·	data	PRE-F Length	LOW SHUT-IN PRE	SSURE DATA SI press.	Stabilize	•			
Compl Sh	ut-in 🗡	time shu	t-in	psig SI press.	O (Yes or N Stabilize				
	date 1:30/ ut-in 5-12-8	time shu	t-in 3 day.	S psig	440 (Yes or N	<u>o)</u>			
Conmenced	at (hour, date) [Lapsed time	* 1:45 PM	FLOW TEST 'NO 5-15-86	Zone produc	ing (Upper or Lower):			
Time (hour, dat		Pres Upper Compl.	Sure Lower Compl.	Prod. Zone Temp.	Remarks				
12:30 P	14	0	_						
5-16-80 9,30 A			300						
5-17-86		0.	280						
Production	rate during te	st	Rhls. in	Hrs.	GravGC	DR			
Gas:	BOPD b	MCFPD; Tested	thru (Orifice TEST SHUT-IN PRI	Hrs					
Upper Hou	r, date	Length		SI press.	Stabilize				
Compl SI	ompl Shut-in ower Hour, date		ut-in of	SI press.	(Yes or M	d?			
3	nut-in	time sh		psig	(Yes or N	10)			
Commenced	at (hour, date)) ** *		Zone produ	cing (Upper or Lower	·):			
Time (hour. da	Lapsed time te) since **	Pre: Upper Compl.	Lower Compl.	Prod. Zone Temp.	Remarks				
					123 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
	·				OIL CON. DIV.				
					OIL CON. DIV				
Productio	n rate during to	est	Bbls. in	Hrs.	Grav. 3 GOR	/			
Gas:		MCFPD; Teste	d thru (Orifice	or Meter):	Gravest. 3 GOR				
REMARKS:	(GAllup Zone S	I - NOT Pro	ducing - No PA	eessure.					
	,		•			- £			
	ertify that the	information h	erein contained	is true and co	mplete to the best	от ту			
nowledge.	John	-2 1986	Operato	r JEROME	P. Mª Hugh				
pproved: Dil Consei	vation Division		- By M.	Operator JEROME P. Mª Hugh By Maxine Mkuller					
∩⊒	iginal Signed by CHARLE			Agent					
<i></i>									
itle [EPUTY OIL & GAS INSP	COLORY DIOL. M.	Date	5-28-86					

Title

1. A parker leakage test shall be commenced on each multiply completed sell within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and absolute recedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any lime test commencation is suspected or when requested by the Commission.

2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.

3. The packer leakage test shall consence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in ontil the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.

4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in.

Such test shall be continued for seven days in the case of a gas well and the producer. at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.

5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.

6. Flow lest No. 2 shall be conducted even though no leak was indicated during flow lest No. 1. Procedure for flow lest No. 2 is to be the same as for flow lest No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

7. Pressures for qua-zone tests must be measured on each zone with a deadweight pressure quage at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly totervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test may be requested on wells which have previously shown questionable test data.

data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test form Revised 11-1-58, with all

the Artec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all two conserver phases which may be reflected by the pressure conserver. the

	Both	Zones	5 <u>T</u>	t in 18 product	pper-SI	taken indi indicate a gauge char ront of t	cated them 11 key pro te. These he Packer	reon. For essure cha e key pres Leakage T	oil zones, the pronges which may be sure changes should est Form.	essure curve reflected by d also be to	should also the recording bulated on the
1000 PSi											
900 13:											
800 PS/											
700 P51											
loo Pei											
E00 PSi				DAKOTA:							
400 Psi											
300 P31							X				
200 Ps;											