

## STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

August 20, 1986

Mr. Ed Alizadeh Amoco Production Co. 2325 East 30th Farmington, NM 87401

Re: Jicarilla Contract 155 #20, N-29-26N-5W

Dear Ed:

The enclosed bradenhead test on the referenced well indicates a casing failure.

In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

If you have any questions, please contact this office.

Yours truly,

Charles Gholson
Oil & Gas Inspector

CG/dj

xc: Well File



## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

3:ADENHEAD TEST REPORT
(Submit 3 copies to above address)

Date of Test June	19 19 86 Operator	Amoco Prop. Co.
	·	- 20 Location UN Sec 29 Twp 2W Range 5W
Prassure Shut-in	or Flowing) Dut Tubi	ng 1200 Intermediate — . Çasing 1050 Bradenhead 1050
		OSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.
TIME:	PRESSURES: ATE CASING	BRADENHEAD INTERMEDIATE FLOWED: FLOWED:
5 Min.	1060	Steady Flow X DRY GAS
10 Min	975	Surges
15 Min	950	Down to Nothing
20 Min		Nothing
25 Min.		Gas
30 hin		Gas & Water DECEIVED
••		WaterAUG 15 1986
if Bradenhead flow	ved water check descrip	OIL CONLIDE
Clear		Remarks: HAS LEAK BETWEEN CASING
resi		AND BRADEN HEAD
Salty	•	
Sulfur		
Black		
11111116 1	011K- W166	13.0 BY MICHAEL MCLEULAND
$= \frac{\pi}{2} \left( \frac{1}{2} \right) \right) \right) \right) \right)}{1} \right) \right) \right)} \right) \right) \right) \right)} \right) \right)} \right) \right)} \right) } \right) } \right) } } } \right) } } } }$	De 10 Rech	13.0 BY MICHAEL MCLEULAND  PLIMPER (Position)