

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

5. Lease Designation and Serial No.

Jicarilla Contract 155

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Attention

Amoco Production Company

Lori Arnold, rm. 1178

3. Address and Telephone No.

P. O. Box 800, Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1160' FSL 1540 FWL S 29 T 26N R 5W

8. Well Name and No.

Jicarilla Contract 155 20

9. API Well No.

30 039 20213

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

Rio Arriba, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Bradenhead Repair

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRUSU on 10/21/92. Blow well down and kill w/40 bbls 2% KCL water. NDWH. NUBOP. Tih w/tbg. Tag fill at 6913'. PBDT 7200'. Toh w/tbg. On 10/22/92 tih tbg w/bp & pckr. Setp bp @ 4860'. Test csg to 1000#. Test casing for leak on 10/23/92. NDBOP. NDCH. Pump KCL down braidenhead & located leak. Cutoff weld. NUCH. NUBOP. SI well for weekend. On 10/26 attempted to weld holes, unsuccessful. Cut off csg just above slips. Weld on csg nipple & replace csg ring plate. NUBOP. Prep to test csg & clean out sand. Complete csg repair on 10/27/92. NUWH. NUBOP. Test csg & braidenhead to 1000# for 5 min. & held. Tih w/retrieving head. Cir sand off plug. Retrieve plug. TOH. Tih w/bailer. TOH w/bailer on 10/28. Tih w/bit to 5000' disp hole w/nitrogen. Tih to 6913' circ w/nitrogen & rotate bit. On 10/29/92, toh w/bit. Tih w/ sn/tbg. Land at 5130'. Sn at 5100'. NDBOP. NUWH. Turn well over to production & prep to check well 11/2/92. On 11/02/92, RDMOSU. Tbg 860#, csg 860# equalized, bh 0#.

14. I hereby certify that the foregoing is true and correct

Signed

Lori Arnold

Title

Business Analyst

Date

12/29/92

(This space for Federal or State office use)

Approved by

SHIRLEY MONDY

Conditions of approval, if any:

ACTING

Title

AREA MANAGER

RIO PUERCO RESOURCE

Date

JAN 27 1993